

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22008654/Kny3q2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	28/10/2022	
			Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMK 4646Z	Veh. Inspected	SKL 2882P	
	Policy No.	P10751080R00	Coverage (\$)	0.00	
	Claim No.	C10017272/JL	Excess (\$)	0.00	
	Assign From	SALIZAWATI HAIZAR	Assign Date	05/09/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ESTIMA (A)	c.c	2362	
	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	ACR500163420	Colour	METALLIC PEARL WHITE	
	Odometer	142493 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/50 R18	TOYO	6 mm	
	L/H Front Tyre	225/50 R18	TOYO	6 mm	
	R/H Rear Tyre	225/50 R18	TOYO	6 mm	
	L/H Rear Tyre	225/50 R18	TOYO	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	02/09/2022	Inspection Date	12/09/2022	
	Survey held at TROPICAL SUCCESS AUTO CARE				
		BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535.			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: