

REF: AGZ/ 22008654/KNY3

C

Menneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 06/23 Person Contacted: _____

Vehicle: IN / OUT

Veh No: PKL 2882P Yr Regn: 06, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Estima C.C. 2362Colour: M.P. white A/C: Insured / Std / NI / NASp. Reading: 142493 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ACR 50 0163420Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim orTyre Size: F: 225/50R18
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 2/9/22

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 12/9/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/9/21 Long @ 3700k Cghw 14/10/22 (Red, 4864.50, 57%)

Date/Time, File Pass to?

1) 25/10/22

Date/Time, File Return to?

2) _____

☐ : Prell. Report☐ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation

S + RS. SI

Firms

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 3700

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M/s : **Auto & General Insurance (Singapore) Pte Ltd**

190, Clemenceau Avenue, #03-01,
Singapore Shopping Centre,
Singapore 239924

Estimate bill : TT 29 / 22 / TP / WT

Registration No : SKL2882P

Attn : Motor Claims Department

Tel : 6221 2111

Fax : 6725 0611

Make / model : Toyota Estima

Mileage :

Date : 07 / 09 / 2022

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SMK4646Z AND SKL2882P ALONG KPE ON 02 SEPTEMBER 2022 AT ABOUT 0830HRS.

1pc	Rear boot		\$	1,619.00	✓
1pc	Rear boot lock		\$	330.00	✓
1pc	Rear boot rubber		\$	180.00	✓
1pc	Rear end panel	625.50	\$	630.00	✓
1pc	Rear end panel top garnish	272.60	\$	345.00	✓
1pc	Rear spare tyre wheel house		\$	1,049.00	✓
1pc	Rear bumper		\$	690.00	✓
2 4pcs	Rear bumper parktronic sensor	2206.00	\$	1,120.00	✓
4pcs	Rear bumper parktronic sensor 'O' ring		\$	108.00	✓
4pcs	Rear bumper parktronic sensor holder		\$	136.00	✓
2pcs	Rear bumper towing cover		\$	90.00	✓
2pcs	Rear bumper reflector		\$	132.00	✓
1pc	Rear bumper sponge		\$	105.00	✓
	Sub A total :		\$	6,534.00	
	Less 25% discount :		\$	1,633.50	
	A total :		\$	4,900.50	
Special net items :					
1pc	Rear boot emblem		\$	56.00	✓
1pc	Rear boot 'Estima' designation		\$	56.00	✓
1pc	Rear boot 'Aeras' designation		\$	67.00	✓
1pc	Rear license smart plate & casing		\$	35.00	✓
	B total :		\$	214.00	
	Remove and refit rear windscreen		\$	200.00	1201
	Total amount of Page 1 :		\$	5,314.50	

(Authorised Signature)
William Tan



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **Auto & General Insurance (Singapore) Pte Ltd**
190, Clemenceau Avenue, #03-01,
Singapore Shopping Centre,
Singapore 239924

Estimate bill : TT 29 / 22 / TP / WT

Registration No : SKL2882P

Attn : Motor Claims Department
Tel : 6221 2111
Fax : 6725 0611

Make / model : Toyota Estima

Mileage :

Date : 07 / 09 / 2022

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SMK4646Z AND SKL2882P ALONG KPE ON 02 SEPTEMBER 2022 AT ABOUT 0830HRS.

Remove and transfer rear boot necessary attachment spart part items.

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit rear boot, rear boot lock, rear end panel top garnish, rear bumper, rear bumper parktronic sensors, rear bumper parktronic sensor 'O' rings, rear bumper parktronic sensor holders, rear bumper towing covers, rear bumper reflectors, rear bumper sponge.

Heat / weld / cut / renew rear end panel, heay / weld cut / renew rear spare tyre wheel house, held weld / beating / pull / straighten / align rear chassis frame by Chassis Aligment jack.

\$ 1,200.00 *6001*

Diagnostic and reset rear bumper parktronic sensor fault error by HHT

\$ 100.00 *501*

Under coating on rear damaged portion.

\$ 150.00 *601*

Putty / primer application, spray painting on rear boot, rear end panel, rear spare tyre wheel house, rear bumper, rear bumper parktronic sensors, rear bumper towing covers (Pearl White).

\$ 1,800.00 *6601*


Balance amount brought from Page 1 :

\$ 5,314.50

Grand final amount :

\$ 8,564.50

Tropical Tech Automobile Services


(Authorised Signature)
William Tan

