

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/ASM22008664/Uea3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11 mth plus.

have notes of R/L
col until 01-09-2023 RTA #3159
MPP # 5801

13/9/22 4/5 @ 2400 informed Allen.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

FASTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6 #01-48 Autobay
 Singapore 417883
 Tel No: 67452063/ 67467158 Fax No: 67458520
 Tax Reg No : 200006262D

Ashu

Not Authorised
 LK
 5/9/22
 1/s & 2400/
 46ms

VEHICLE No: SJX 8649G

1PC	BONNET	11	\$1,029.10	X
1PC	BONNET INNER RUBBER	11	\$66.50	X
2PCS	BONNET HINGES @\$85.00	11	\$170.00	X
1PC	BONNET LOCK	11	\$166.10	X
1PC	FRONT BUMPER	10/22	\$651.10	—
1PC	FRONT BUMPER CENTRE GRILLE	10/22	\$133.10	—
2PCS	FRONT BUMPER SIDE RETAINERS @\$69.00	11	\$138.00	—
1PC	FRONT BUMPER REINFORCEMENT	11	\$399.20	—
1PC	FRONT BUMPER TOP RUBBER	11	\$68.00	—
1PC	FRONT BUMPER LOGO	11	\$68.10	—
1PC	FRONT GRILLE	11	\$485.10	—
2PCS	HEADLAMPS @\$645.10	11	\$1,290.20	12C
1PC	FRONT BRACE PANEL	11	\$151.10	X
1PC	AIR CON CONDENSER	11	\$1,486.10	X
1PC	RADIATOR	11	\$1,866.10	X
1PC	FRONT SUPPORT PANEL	11	\$745.10	X
			\$8,912.90	
			LESS 25%	\$6,684.67

566.10

381.00

11s cre

1SET	S.NETT			
1SET	FRONT BUMPER CLIPS	11	\$50.00	✓
1PC	FRONT BUMPER LICENCE PLATE	11	\$50.00	40
1SET	BONNET INSULATOR CLIPS	11	\$50.00	X

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	11	\$80.00 X
TO REFILL AIR CON GAS	11	\$120.00 X
TO RESET & REPROGRAMME SYSTEM	11	\$180.00 X
LABOUR FOR PANEL BEATING & REPLACED PARTS		\$850.00 480
TO PUTTY & SPRAY PAINTING		\$1,080.00 550
TOTAL		\$8,114.67

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

p- 2484.50
 25%
 1863.37
 90
 1050
 3003.37
 2402.