

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# SLG7738E

Accident Date 3/9/2022

Location SERANGOON NORTH BLK 108 CARPARK

Model: TOYOTA WISH 1.8

10/10/2016

3P: SLB9228Z (UOI)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper	842.20		648 ✓
2	10 pcs	Front bumper clips		40.00	net ✓
3	1 pc	Front bumper n/s retainer	137.25		80 ✓
4	1 pc	Front bumper n/s fog lamp	422.80	BR	319 ✓
5	1 pc	Front bumper n/s fog lamp garnish cover	195.00		151 ✓
6	1 pc	Front bumper n/s fog lamp bracket (C/with fog lamp)	192.75		7 X nn
7	1 pc	Front grille	789.60	BR	472 ✓
8	4 pcs	Front grille clips		NEC 16.00	✓ nett
9	1 pc	Front n/s head lamp	1,100.00	✓	
Sub Total:			3,679.60	56.00	0.00
			25%	0%	10%
2770 After Less %:			2,759.70	56.00	0.00
			-25%		
2077.50 + nett 46					

Labour					
1		To dismantle, straighten & welding.	800.00	250	400
2		To spray painting.	600.00	250	400
3		To check for fault code and re set electrical system.	180.00	1	
4		To check wiring.	50.00	30	
5		To re seal anti rust.	50.00	20	
Sub Total:			1,680.00		
Total:			4,495.70	850	
After Less 20%:			3,596.56		

Chan San Choon
Director
DipEng, AAE MIM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Insurance claim(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: Accredited Certification



bizSAFE AL 8778 1999

ST R

24 hr accident call



PAYNOW