



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:VALE OH

Ref: CC4/ASM22008675/Upa3q2
Date: 21/11/2022
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3863X	Veh. Inspected	GBF 844B
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S2M049PK	Excess (\$)	0.00
Assign From		Assign Date	05/09/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTFAT35Y00K206569	Colour	SILVER
Odometer	243099 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	GREEN MAX	6 mm
L/H Front Tyre	195 R15	GREEN MAX	6 mm
R/H Rear Tyre	155 R12 (D)	HONOUR	6/6 mm
L/H Rear Tyre	155 R12 (D)	HONOUR	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/08/2022	Inspection Date	06/09/2022
Survey held at	JEMENTAH MOTOR WORKS BLK 14 DEFU LANE 10 #01-406 SINGAPORE 539195		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**