

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SFZ2000D
Accident Date : 03-Sep-2022

No. : 06648

Date : 05-Sep-2022

Our Ref : 022140 (UOI) / CHAN

PAGE : 1

LOO, ZHONGYI JAVIER
50 CANBERRA DRIVE
#06-20
Singapore 768438

*Not with us
11/9/22 84300p
Manny After Party
6 days*

ESTIMATED COST OF REPAIR FOR MAZDA 2 SLK3900H

- 1 pc Front n/s fender
- 1 pc Front n/s fender inner shield
- 1 pc Front n/s door *1164*
- 1 pc Front n/s door glass regulator gear
- 1 pc Front n/s door glass regulator motor
- 1 pc Front n/s door frame tape
- 1 pc Front n/s door lower hinge
- 1 pc Front n/s door checker
- 1 pc Front n/s door rubber
- 1 pc Rear n/s door *1216*
- 1 pc Rear n/s door lower hinge
- 1 pc Rear n/s door frame tape
- 1 pc Rear n/s door rubber
- 1 pc N/s centre pillar

By	359.00	✓
By	69.00	X
By	1,164.00	✓
Dis	178.00	✓
By	169.00	✓
By	45.00	✓
By	56.00	✓
By	38.00	✓
By	141.00	X
By	1,216.00	X
By	57.00	X
By	48.00	✓
By	139.00	X
By	751.00	X

Less 20% :

4,430.00
886.00

- 1 pc Rear n/s sport rim *P2 950*

3,544.00
1,020.00 sn

To remove roof lining, front and rear seats, trim board and carpet

120.00 *Dot*

To apply undersealing

60.00 ✓

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SFZ2000D

Page : 2

To check and adjust wheel alignment	65.00 601
To putty and spray replaced parts	1,300.00 1000
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts	900.00 600
To transfer rim	50.00 201
Total :	S\$ 7,059.00 =====

Singapore Dollars Seven Thousand and Fifty Nine
Only

Usum-4350
→
KENNETH PUS COMPANY
TCS

P 7618.40
SN 1000.00
L 1800.00
5758.40
1091.68
4366.72