



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22008693/Evy3q2	
			Date: 28/10/2022	
			Code: SMO	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SGZ 7778Z
	Policy No.	D22MTPV01010191	Coverage (\$)	0.00
	Claim No.	CMTD2202595/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	05/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ GLC250	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WDC2539462F240706	Colour	BLACK
	Odometer	162378 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R19	CONTINENTAL	4 mm
	L/H Front Tyre	235/55 R19	CONTINENTAL	4 mm
	R/H Rear Tyre	235/55 R19	CONTINENTAL	4 mm
	L/H Rear Tyre	235/55 R19	CONTINENTAL	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/07/2022	Inspection Date	06/09/2022
	Survey held at	KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147		
5a. Remarks				
	A)THE MARKET VALUE IS S\$143,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	