



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

SOMPO INSURANCE (S) PTE LTD

50 RAFFLES PLACE #03-03

SINGAPORE LAND TOWER

SINGAPORE 048623

VEHICLE NO. : SGZ7778Z

ACCIDENT DATE : 23-07-2022 11:30

THIRD PARTY REF. : SJP5636E

DATE : 05-08-2022

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SGZ7778Z MERCEDES MERCEDES BENZ GLC250 AMG 4MATIC

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT HEADLAMP RH / CUT	1440.00 1600
2	1	FRONT BUMPER ? (Disman/le) Repair	785.00
3	1	FRONT BUMPER SIDE RETAINER RH 1 nn	15.00
4	1	FRONT BUMPER FOG LAMP COVER RH 1 nn	48.00
5	1	FRONT BUMPER SENSOR RH X nn	98.00
6	1	FRONT BUMPER CHROME LOWER RH X nn	60.00
7	10	FRONT BUMPER RIVET @\$5.00 / 11 nn	50.00
8	1	FRONT RIM (CHECK PRICE) X nn	0.00
			2,496.00
			ADD 10 %
			249.60
			TOTAL (A)
			2,745.60

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	50.00 /
2	1	TO CHECK ALIGNMENT	100.00 X
3	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	520.00 250
4	1	SPRAYPAINTING CHARGES	580.00 250
			TOTAL (D)
			1,250.00
			ESTIMATE TOTAL
			3,995.60

Remark: Price might be different due to stock availability

4171.60