





# ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road  
#08-1339 Singapore 470130  
Tel: 9450 7920  
\* zoomautowerks@gmail.com

*not Authorised*

19 October 2022

REG NO.: SNA 1037 S  
MAKE/MODEL: KIA CERATO

*her*  
*over*  
*6/9/22*  
*2/5 \$11,000*  
*15 days*

## ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

| QTY | DESCRIPTION                                  | AMT(\$)              |
|-----|----------------------------------------------|----------------------|
|     | <u>LIST ITEMS</u>                            |                      |
| 1   | Front bumper <i>her</i>                      | \$ 858.60 <i>x</i>   |
| 1   | Front bumper fog lamp -LH <i>her</i>         | \$ 186.90 <i>x</i>   |
| 1   | Front bumper fog lamp cover <i>her</i>       | \$ 45.00 <i>x</i>    |
| 1   | Front bumper logo <i>her</i>                 | \$ 75.00 <i>x</i>    |
| 2   | Front bumper side retainers <i>her</i>       | \$ 65.60 <i>x</i>    |
| 1   | Front wheel hub <i>her</i>                   | \$ 160.00 <i>✓</i>   |
| 1   | Front wheel bearing <i>her</i>               | \$ 115.00 <i>✓</i>   |
| 1   | Front shock absorber <i>her</i>              | \$ 282.00 <i>x</i>   |
| 1   | Front knuckle arm <i>her</i>                 | \$ 325.00 <i>✓</i>   |
| 1   | Front lower arm <i>her</i>                   | \$ 295.00 <i>✓</i>   |
| 1   | Rear windscreen moulding <i>her</i>          | \$ 98.60 <i>✓</i>    |
| 1   | Rear boot lid <i>her</i>                     | \$ 793.80 <i>x</i>   |
| 1   | Rear boot hinges <i>her</i>                  | \$ 125.00 <i>x</i>   |
| 1   | Rear boot lamp <i>her</i>                    | \$ 186.50 <i>✓</i>   |
| 1   | Rear boot inner lock <i>her</i>              | \$ 126.50 <i>x</i>   |
| 1   | Rear boot rubber <i>her</i>                  | \$ 128.60 <i>x</i>   |
| 1   | Rear boot "KIA" emblem <i>her</i>            | \$ 52.50 <i>✓</i>    |
| 1   | Rear boot "CERATO" emblem <i>her</i>         | \$ 42.50 <i>✓</i>    |
| 1   | Rear boot "K3" emblem <i>her</i>             | \$ 32.50 <i>✓</i>    |
| 1   | Rear taillamp -RH <i>her</i>                 | \$ 487.60 <i>✓</i>   |
| 1   | Rear taillamp panel <i>her</i>               | \$ 225.00 <i>✓</i>   |
| 1   | Rear end panel <i>her</i>                    | \$ 598.50 <i>✓</i>   |
| 1   | Rear end panel inner garnish <i>her</i>      | \$ 152.50 <i>x</i>   |
| 1   | Rear smart keyless sensor <i>her</i>         | \$ 185.50 <i>x</i>   |
| 1   | Rear bumper <i>her</i>                       | \$ 658.00 <i>✓</i>   |
| 1   | Rear bumper inner sponge <i>her</i>          | \$ 145.50 <i>x</i>   |
| 1   | Rear bumper reflector <i>her</i>             | \$ 115.00 <i>✓</i>   |
| 1   | Rear bumper reinforcement <i>her</i>         | \$ 356.00 <i>✓</i>   |
| 1   | Rear bumper reinforcement stay <i>her</i>    | \$ 152.50 <i>✓</i>   |
| 1   | Rear bumper reinforcement bracket <i>her</i> | \$ 22.90 <i>x</i>    |
| 2   | Rear bumper side retainers <i>her</i>        | \$ 77.00 <i>✓</i>    |
| 4   | Rear bumper PDC sensors <i>her</i>           | \$ 746.00 <i>✓</i>   |
| 1   | Rear bumper lower extension <i>her</i>       | \$ 198.50 <i>✓</i>   |
| 1   | Rear fender -RH <i>her</i>                   | \$ 1025.00 <i>✓</i>  |
| 1   | Rear fender air gate <i>her</i>              | \$ 48.50 <i>✓</i>    |
| 1   | Rear fender inner shield <i>her</i>          | \$ 58.60 <i>✓</i>    |
| 1   | Rear fender inner trim <i>her</i>            | \$ 186.00 <i>x</i>   |
| 1   | Rear floor board <i>her</i>                  | \$ 280.50 <i>x</i>   |
| 1   | Rear floor panel <i>her</i>                  | \$ 885.00 <i>x</i>   |
| 1   | Rear door -RH <i>her</i>                     | \$ 1,035.00 <i>x</i> |
| 1   | Rear door rubber <i>her</i>                  | \$ 165.00 <i>x</i>   |
|     |                                              | \$                   |

LIST ITEMS

|   |                              |            |          |        |        |
|---|------------------------------|------------|----------|--------|--------|
| 1 | Rear door lock               | n1         | \$       | 305.00 | X      |
| 1 | Rear exhaust silencer        | n          | \$       | 726.50 | X      |
| 2 | Rear exhaust mountings       | n1         | \$       | 87.00  | X      |
| 1 | Rear exhaust head shield     | n1         | \$       | 118.30 | X      |
| 1 | Rear wheel hub with bearings | 0/5 Dye    | \$       | 459.00 | 579.00 |
| 1 | Rear shock absorbers         | 0/5 tw     | \$       | 286.20 | 443.20 |
| 1 | Rear axle beam               | 2nf/tw     | \$       | 833.00 |        |
|   |                              |            | \$       |        |        |
|   | Rear broke hose 0/5          | 62.50 Torn | Less 10% | \$     |        |
|   | Rear broke caliper assy 0/5  | 640 Dye    | \$       |        |        |
|   | Rear absorber stopper 0/5    | 48.00 Torn |          |        |        |

SPECIAL NETT ITEMS

|   |                                       |                    |    |          |         |
|---|---------------------------------------|--------------------|----|----------|---------|
| 1 | Front bumper lower spoiler            | Dis                | \$ | 750.00   | 500     |
| 1 | Front tyre                            | 8u                 | \$ | 500.00   | X       |
| 1 | Front sport rim - LH                  | cut/moped          | \$ | 1,050.00 | 400     |
| 1 | Rear windscreen sealant               | n                  | \$ | 80.00    | 40      |
| 1 | Rear bumper clip (1 set)              | n                  | \$ | 50.00    | 40      |
| 1 | Rear bumper lower spoiler             | Dis                | \$ | 750.00   | 500     |
| 1 | Rear fender inner shield clip (1 set) | n1                 | \$ | 45.00    | X       |
| 2 | Rocker panel side skirts 0/5          | Torn               | \$ | 1,500.00 | 500     |
| 1 | Rear exhaust chrome tail pipe         | n1                 | \$ | 120.00   | X       |
| 2 | Rear tyres                            | 0/5 run LP 200x70% | \$ | 1,000.00 | 1405/N  |
| 2 | Rear sport rims                       | 0/5 one MS cut     | \$ | 2,100.00 | 800 S/N |
|   |                                       |                    | \$ | 7,945.00 |         |

S/NLABOUR CHARGES

|    |                                                                                              |    |          |      |
|----|----------------------------------------------------------------------------------------------|----|----------|------|
| 1  | To remove, replaced damaged lamps and check up rear wiring.                                  | \$ | 80.00    | 30   |
| 2  | To remove and refit inner garnishes.                                                         | \$ | 180.00   | 100  |
| 3  | To remove and refit rear reverse sensor.                                                     | \$ | 150.00   | 50   |
| 4  | To transfer boot lid mechanism and wiring assembly.                                          | \$ | 80.00    | X    |
| 5  | To remove and refit front undercarriage.                                                     | \$ | 300.00   | 120  |
| 6  | To remove and refit rear undercarriage.                                                      | \$ | 350.00   | 250  |
| 7  | To conduct wheel alignment.                                                                  | \$ | 180.00   | 80   |
| 8  | To remove and refit rear windscreen glass.                                                   | \$ | 180.00   | 120  |
|    | To remove, refit door fittings and replace damaged parts, transfer all fittings to new door. | \$ | 180.00   | X    |
| 9  | To apply undercoating.                                                                       | \$ | 200.00   | 60   |
| 10 | Panel beating.                                                                               | \$ | 1,800.00 | 1600 |
| 11 |                                                                                              | \$ | 1,600.00 |      |
| 12 | To re-spray painting on the affected areas.                                                  | \$ | 5,280.00 |      |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**GRAND TOTAL:**

Acknowledged by Repairer  
Signature:  
Date:

P-7611  
102  
P-6849.9  
S.N.2920  
L-40.0