

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No: 53231488C GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

21/09/2022

01-43

Singapore 417883

Accident date : 01/09/2022

Estimated repair cost for vehicle no: SKU9966M TOYOTA HARRIER 2.0 ELEGANCE AT ABS

CHASSIS: ZSU600065583 (2015)

SUPPLEMENTARY

S/N	Qty	Items	U/price	Amount
1	1	LH REAR FENDER AIR VENT <i>Not mtr</i>	\$114.10	\$114.10 <i>X</i>
2	1	LH REAR SIDE GARNISH BOX <i>Delivered</i>	\$398.60	\$398.60 <i>✓</i>
3	1	RH REAR SIDE GARNISH BOX <i>Delivered</i>	\$398.60	\$398.60 <i>✓</i>
4	1	LH REAR TOOLS GARNISH TRAY <i>Delivered</i>	\$578.20	\$578.20 <i>✓</i>
5	1	RH REAR SIDE TRAY <i>Delivered</i>	\$339.60	\$339.60 <i>✓</i>
6	1	REAR SPARE TYRE LOCK NUT <i>Best</i>	\$143.70	\$143.70 <i>✓</i>
7	1	REAR WEATHER STRIPE <i>Repeated</i>	\$394.10	\$394.10 <i>X</i>
8	1	REAR KEYLESS SENSOR <i>Cracked</i>	\$157.10	\$157.10 <i>✓</i>
9	2	REAR FENDER INNER TRIM BOARD <i>Cracked</i>	\$791.70	\$1,583.40 <i>✓</i>

TOTAL : \$4,107.40

LESS 25 % \$1,026.85

SUB-TOTAL : \$3,080.55

3599.20

Supplementary: 2689.40