

ASS. REC. BY:

REF:

AG21 22 008699/K943

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Book: 6A Auto

of

574A

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8-7 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKX 2017B Yr Regn: 12, 15

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Harrier

C.C

1986

Colour

M. P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

506855

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

85460 0060479

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/65R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Le90

Front

Rear

R/Bal.

P

mm

R/Bal.

P

mm

L/Bal.

P

mm

L/Bal.

P

mm

D.O.A.

2/9/22

D.O.I.

6/9/2022

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

6/15

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

/ Will send GIA & EM over

2/19 11h 88500 C. H. (Net @ 16293.08, 657.)

Date/Time, File Pass to?

1) 26/9 11h 15m

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.A. (\$) 7P 8500

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee:

Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Not Wholesaler
 11 Ring @ 8500/hr
 Delivery After Paint
 7 days

BOEKI AUTO PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C,

#01-12 Singapore 575645

Email: admin@lmautosolution.com

Tel: 90162222

VEHICLE NUM:

SKX 2617 B

MAKE & MODEL:

TOYOTA HARRIER

MILEAGE:

ENGINE NUM:

CHASSIS NUM:

DESCRIPTION - PARTS	QTY	PRICE	
TAIL GATE 1466.10 B1	1	\$ 1,821.80	✓
TAIL GATE LOCK 418.60 DCL	1	\$ 954.40	✓
TAIL GATE EMBLEM - HARRIER MCL	1	\$ 68.80	✓
TAIL GATE W/STRIPE 341.60 DCL/1	1	\$ 341.60	50% in 170-8000
TAIL GATE HINGE LH + RH R	2	\$ 199.00	X
TAIL GATE INNER TRIM MCL	1	\$ 406.50	✓
TAIL GATE W/S GLASS MOULDING 160 MCL	1	\$ 297.50	✓
TAIL GATE LAMP LH + RH R	2	\$ 781.20	X
REAR BUMPER 904. BCL	1	\$ 1,381.50	✓
REAR BUMPER RETAINER LH + RH R	2	\$ 203.60	X
REAR BUMPER BRACKET LH + RH R	2	\$ 169.80	X
REAR BUMPER LOWER 321 RCL/1	1	\$ 459.60	✓
REAR BUMPER REFLECTOR LH + RH R	2	\$ 193.60	X
REAR BUMPER SPONGE CMT	1	\$ 180.50	✓
REAR BUMPER CLIP MCL	1	\$ 80.00	✓ 50% in
TAIL LAMP LH + RH R	2	\$ 983.60	X
REAR END PANEL 715. B1	1	\$ 791.80	✓
REAR END PANEL TOP GARNISH MCL	1	\$ 360.80	✓
SPARE WHEEL PANEL R	1	\$ 785.60	X
SPARE WHEEL PANEL TOP BOARD R	1	\$ 441.50	X
REAR FENDER INNER TRIM LH + RH R	2	\$ 1,124.60	X
FRONT BUMPER 1398.70 BCL/1	1	\$ 1,845.50	✓
FRONT BUMPER RETAINER LH + RH MCL/1	2	\$ 197.80	4
FRONT BUMPER BRACKET LH + RH R	2	\$ 179.60	X
FRONT BUMPER SPONGE CMT	1	\$ 163.20	✓
FRONT BUMPER REINFORCEMENT R	1	\$ 581.60	X
FRONT BUMPER GRILLE R	1	\$ 281.30	X

FRONT BUMPER CLIP [SET]	Nu	1	\$	80.00	✓ 505N
FRONT GRILLE ASSY	598. Mgc M	1	\$	1,123.60	✓
HEADLAMP ASSY LH + RH	NLS Mgc M	2	\$	6,374.80	✓ 3187.40
FRONT SUPPORT PANEL	R	1	\$	881.90	X
AIRCON CONDENSOR	Sn	1	\$	1,447.80	X
RADIATOR	Sn	1	\$	2,059.70	X
SUBTOTAL			\$	27,244.10	
25%			\$	6,811.03	
PARTS TOTAL			\$	20,433.08	
SPECIAL NETT		QTY	PRICE		
REAR NUMBER PLATE	Sn	1	\$	60.00	X
TAIL GATE W/S GLASS SEALANT	Nu	1	\$	80.00	405N
REAR END PANEL SEALANT	Nu	1	\$	80.00	305N
REAR WHEEL PANEL SEALANT	Nu	1	\$	80.00	X
REVERSE SENSOR	Shot	1	\$	250.00	2005N
FRONT NUMBER PLATE	Nu	1	\$	80.00	455N
SPECIAL NETT 1			\$	630.00	
LABOUR		QTY	PRICE		
TO KNOCK, STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA		1	\$	1,600.00	900L
TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA		1	\$	1,400.00	1000L
TO RUST PROOF ACCIDENT AFFECTED AREA		1	\$	90.00	60L
TO R & R TAIL GATE W/S GLASS		1	\$	120.00	✓
TO R & R TAIL GATE MECHANISM		1	\$	120.00	60L
TO R & R REAR LUGGAGE COMPARTMENT		1	\$	120.00	60L
TO R & R REVERSE SENSOR AND CHECK FUNCTION		1	\$	80.00	50L
TO R & R AIRCON CONDENSOR AND REFILL GAS		1	\$	120.00	X
TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS		1	\$	80.00	40L
LABOUR TOTAL			\$	3,730.00	
GRAND TOTAL COST			\$	24,793.08	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: