

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 12.09.2022

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SNF5018U
MODEL : HONDA FREED
DATE OF ACCIDENT : 01.09.2022
TIME OF ACCIDENT : 16:30HRS

Veron GB73156371

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Rehd</i>	1	\$ 925.30	\$ 925.30 828
2	REAR BUMPER CENTER BEAM <i>neu</i>	2	\$ 139.70	\$ 279.40 +
3	REAR BUMPER REFLECTOR <i>neu</i>	2	\$ 42.80	\$ 85.60 +
4	REAR BUMPER EXHAUST COVER GARNISH <i>neu</i>	1	\$ 58.10	\$ 58.10 +
5	REAR BUMPER TOWING COVER <i>neu</i>	1	\$ 36.80	\$ 36.80 +
6	REAR BUMPER INNER SIDE GARNISH <i>RH build</i>	2	\$ 60.20	\$ 120.40 60.20
7	REAR BUMPER SIDE RETAINER (UPPER) <i>neu</i>	2	\$ 39.70	\$ 79.40 x
8	REAR BUMPER SIDE RETAINER (LOWER) <i>end</i>	2	\$ 42.30	\$ 84.60 ✓
9	REAR FENDER INNER TRIM <i>RH build</i>	2	\$ 326.70	\$ 653.40 326.70
10	TAIL LAMP <i>RH build</i>	2	\$ 580.40	\$ 1,160.80 580.40
11	TAIL LAMP PANEL RH <i>Perked</i>	1	\$ 386.40	\$ 386.40 ✓
12	TAIL LAMP INNER PANEL RH <i>Regis</i>	1	\$ 435.10	\$ 435.10 +
13	TAIL LAMP LOWER PANEL RH <i>Regis</i>	1	\$ 241.10	\$ 241.10 +
14	TAIL LAMP INNER LOWER PANEL RH <i>Regis</i>	1	\$ 336.80	\$ 336.80 +
15	TAIL GATE <i>Dented</i>	1	\$ 1,180.60	\$ 1,180.60 ✓
16	TAIL GATE LAMP <i>RH build</i>	2	\$ 368.40	\$ 736.80 368.40
17	TAIL GATE LOGO <i>neu</i>	1	\$ 59.20	\$ 59.20 ✓
18	TAIL GATE EMBLEM 'FREED' <i>neu</i>	1	\$ 52.30	\$ 52.30 ✓
19	TAIL GATE EMBLEM 'HYBRID' <i>neu</i>	1	\$ 75.70	\$ 75.70 ✓
20	TAIL GATE OUTER MOULDING (CHROME) <i>ht</i>	1	\$ 370.40	\$ 370.40 ✓
21	TAIL GATE DAMPER (ELECTRONIC) SET <i>ht</i>	1	\$ 120.10	\$ 120.10 +
22	TAIL GATE STOPPER <i>ht neu</i>	2	\$ 13.20	\$ 26.40 +
23	TAIL GATE WEATHER STRIP <i>ht</i>	1	\$ 168.70	\$ 168.70 ✓
24	TAIL GATE INNER TRIM <i>build</i>	1	\$ 295.30	\$ 295.30 ✓
25	TAIL GATE TOP LOCK <i>Perked</i>	1	\$ 157.60	\$ 157.60 ✓

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SNF5018U
 MODEL : HONDA FREED
 DATE OF ACCIDENT : 01.09.2022
 TIME OF ACCIDENT : 16:30HRS

26	TAILGATE LOWER LOCK <i>Replaced</i>	1	\$ 26.70	\$ 26.70	✓
27	TAILGATE WINDSCREEN MOULDING <i>MC</i>	1	\$ 145.70	\$ 145.70	✓
28	REVERSE CAMERA <i>Not a</i>	1	\$ 786.90	\$ 786.90	+
29	REAR END PANEL (OUTER) <i>Replaced</i>	1	\$ 623.70	\$ 623.70	✓
30	REAR END PANEL TOP GARNISH <i>Replaced</i>	1	\$ 169.30	\$ 169.30	✓

5559.80
4767.82

TOTAL PRICE \$ 9,878.60
 LESS 20% \$ 1,975.72
SUB TOTAL PRICE \$ 7,902.88

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>MC</i>	1	\$ 80.00	\$ 80.00	+
2	REAR BUMPER CLIPS (SET) <i>MC</i>	1	\$ 60.00	\$ 60.00	30
3	TAILLAMP CLIP (SET) <i>MC</i>	1	\$ 40.00	\$ 40.00	20
4	TAIL GATE OUTER MOULDING CLIP (SET) <i>MC</i>	1	\$ 50.00	\$ 50.00	20
5	TAIL GATE INNER TRIM CLIP (SET) <i>MC</i>	1	\$ 60.00	\$ 60.00	30
6	TAIL GATE WINDSCREEN SEALANT <i>MC</i>	1	\$ 80.00	\$ 80.00	40
7	TAILGATE WINDSCREEN INNER SHIELD <i>MC</i>	1	\$ 60.00	\$ 60.00	30
8	REAR FENDER INNER TRIM CLIP (SET) <i>MC</i>	1	\$ 80.00	\$ 80.00	30
9	REAR END PANEL INSULATION SEAL <i>MC</i>	1	\$ 150.00	\$ 150.00	60
10	REAR END PANEL TOP GARNISH CLIP (SET) <i>MC</i>	1	\$ 40.00	\$ 40.00	10
11	REVERSE SENSOR <i>Replaced</i>	1	\$ 220.00	\$ 220.00	20

470

TOTAL \$ 920.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, WELDING, CUTTING, GRAZING ADJUST, KNOCK STRAIGHTEN	\$ 1,800.00	900
2	TO PUTTY, SPRAY PAINT, POLISH, WAX	\$ 1,200.00	900
3	TO APPLY RUST PROOFING/ UNDER COAT	\$ 250.00	80
4	WIRNING, BULB CHECKING	\$ 80.00	30
5	REMOVE AND REFIX UPHOLSTERY, CUSHION, SEAT TO FACILITATE REPAIR	\$ 350.00	80
6	TRANSFER TAILGATE MECHANISM	\$ 80.00	60

TO : CHINA TAIHING MOTOR CLAIMS DEPTS
 VEHICLE NO : SNF5018U
 MODEL : HONDA FREED
 DATE OF ACCIDENT : 01.09.2022
 TIME OF ACCIDENT : 16:30HRS

7	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
9	REMOVE AND REFIX REAR REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
10	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
11	REMOVE AND REFIX CAR VIDEO RECORDER	\$ 80.00	50
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 4,420.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,822.88
 TOTAL LABOUR COST : \$ 4,420.00
 TOTAL REPAIR COST : \$ 13,242.88

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

Admin

H/S 12/09/22

06 Days

total: 7507.52

L/S! 6K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before start of repair
- To disclose any damage to the vehicle
- Parts prices are subject to change
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items may be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____