

ASS. REC. BY:

REF:

AG/22008703/Ke

C

Kennerth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Cheng Hoe

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKQ 7483G Yr Regn: 12, 14

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Merda ^(A) 3 c.c. 1496

Colour: M. Gray A/C: Insured / Std / NI / NA

Sp. Reading: 14841P T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BM 42A 8F 0139746

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 3 mm

L/Bal. 3 mm

D.O.A. 5/9/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or O/S/FR

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 7/9/2022

Date / Time Action / Instruction

19/9 LI Insp @ 4000 Ckm

Date/Time, File Pass to?

: Preli. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:

Transportation:

S - RS. \$ _____

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SKQ 7463 G
 TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

Estimate No: ES2290909/WS
 Date: 06 Sep 2022
 Policy No: 5105987385-03
 Veh Reg No: SKQ7463G
 Make/Model: MAZDA MAZDA 3 4-DOOR SEDAN 1.5L SP.6EAT
 Chassis No: JM6BM42A8F0139746
 Engine No: P520225057
 Reg. Date: 23/12/2014

WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 05/09/2022
 TP Veh Reg No: GBB9592P

NOT Notarised
 11 Sep @ 4000/-
 Resurvey After Paint
 4 days

Estimate Repair Cost to Vehicle No :SKQ7463G

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER <i>8PF</i>	897.00	1 PC	<i>CRS</i> 897.00	—
2 FRONT BUMPER RH RETAINER	35.00	1 PC	<i>CRS</i> 35.00	—
3 FRONT BUMPER CLIPS	3.50	6 PCS	<i>CRS</i> 21.00	—
4 FRONT BUMPER RH FOG LAMP	368.00	1 PC	<i>my dds</i> 368.00	✓
5 FRT BUMPER RH FOG LAMP GARNISH	63.00	1 PC	<i>CRS</i> 63.00	✓
6 FRONT BUMPER RH FOG LAMP CHROME GARNISH	113.00	1 PC	<i>CRS</i> 113.00	✓
7 RH HEADLAMP WASHER PUMP	254.00	1 PC	<i>CRS</i> 254.00	✓
8 RH HEADLAMP WASHER PUMP COVER	89.00	1 PC	<i>CRS</i> 89.00	✓
9 FRONT GRILLE RH INNER RETAINER	25.00	1 PC	<i>Dis</i> 25.00	✓
10 FRONT GRILLE RH INNER BRACKET	37.00	1 PC	<i>CRS</i> 37.00	✓
11 RH HEADLAMP <i>2354</i>	2,354.00	1 PC	<i>BR</i> 2,354.00	✓
12 FRONT RH FENDER	349.00	1 PC	<i>R</i> 349.00	✓
13 FRONT RH FENDER LINER	<i>Dis/CRS</i> 135.00	1 PC	135.00	—
14 FRONT RH FENDER LINER CLIPS	3.50	6 PCS	<i>CRS</i> 21.00	—
			4,761.00	
		Less 20%	952.20	3,808.80
Labour				
15 REMOVE DAMAGED PARTS & ATTACHMENTS,PANEL BEAT & REPAIR FRT SUPPORT PANEL,RH INNER SIDE PANEL,BONNET	750.00	1 LA	750.00	<i>500/-</i>
16 PAINTING - FRT BUMPER,FRT RH FENDER,BONNET,BUMPER TOP PAD & FRT RH INNER PANEL	800.00	1 LA	800.00	<i>600/-</i>
17 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,580.00	1,580.00
		Total	SS 5,388.80	
		Add GST @ 7%	377.22	
		Total Amount Payable	SS 5,766.02	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd
 [Signature]
 AUTHORISED SIGNATURE