

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0765/2022/EQ
DATE : 2-Sep-22
WIP : 40176

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 05/09/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TOH TECK KIONG
ADDRESS : BLK 10 CHAI CHEE ROAD
#02-09
SINGAPORE 467010
TELEPHONE : HP +65 91771643
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220030428
VEHICLE NO : SLZ 173 E
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 25/3/2022
ENGINE NO : DEM 035964
CHASSIS NO : WAUZZZF58NA010536
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Sep-22
PLACE OF ACCIDENT : PIE (CHANGI) ENTERING KPE (TPE),
IN THE START OF THE TUNNEL

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLZ 173 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00 250	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,600.00 /	
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00 /	
5	TO REMOVE AND REINSTALL BOTH DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$ 560.00 280	
TOTAL LABOUR CHARGES (LH ch) / :		\$ 4,640.00	


55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLZ 173 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT DOORS AND BOTH UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,200.00 S x 500	1500
7	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, BOTH FRONT DOORS AND BOTH UPPER A-PILLAR.	\$ 7,500.00 S x 550	2750
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	/
TOTAL LABOUR CHARGES		: \$ 19,724.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAN@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 173 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,493.00	1994.40.
2	FRONT BUMPER SECURING STRIP	2	\$ 79.00	63.20
3	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 293.00	234.00
5	FRONT BUMPER SPOILER	1	\$ 599.00	
6	RADIATOR AIR GUIDE - LH / RH	2	\$ 144.00	
7	FRONT BUMPER CLOSING ELEMENT	1	\$ 293.00	
8	RADIATOR AIR GUIDE GRILLE - LH / RH	2	\$ 302.00	
9	RADIATOR AIR GUIDE GRILLE OUTER TRIM - LH / RH	2	\$ 108.00	
10	RADIATOR GRILLE TRIM - CENTER	1	\$ 127.00	
11	RADIATOR GRILLE	1	\$ 1,881.00	1504.80.
12	RADIATOR GRILLE COVER CAP	1	\$ 141.00	112.40
13	RADIATOR GRILLE BRACKET	1	\$ 19.00	14.64
14	FRONT CAMERA	1	\$ 1,264.00	
15	FRONT BUMPER FOAM FILLER PIECE	1	\$ 163.00	130.40
16	FRONT BUMPER CARRIER	1	\$ 899.00	719.20
17	FRONT BUMPER BRACKET - LH / RH	2	\$ 508.00	406.40
18	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 82.00	32.24
19	FRONT BUMPER TOP COVER	1	\$ 143.00	114.00
20	CAUTION SIGN STICKER	1	\$ 16.00	12.40.
SUB TOTAL SPARE PARTS			\$ 9,773.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 173 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	AIR CONDITIONER STICKER / NC	1	\$	9.00	6.64
22	LOCK CARRIER / OK (B44)	1	\$	154.00	122.80
23	FRONT BUMPER SUPPORT - LH / RH / Nec	2	\$	64.00	51.04
24	FRONT PARKING AID SENSOR - INNER / OUTER X NN	4	\$	1,062.00	
25	FRONT PARKING AID SEAL RING X NN	4	\$	10.00	
26	FRONT BUMPER WIRING SET X NN	1	\$	449.00	
27	HORN HIGH TONE - LH X NN	1	\$	134.00	
28	HORN LOW TONE - RH X NN	1	\$	139.00	
29	HORN BRACKET - LH / RH X NN	2	\$	66.00	
30	FRONT FENDER - LH / RH X NN	2	\$	2,378.00	
31	FRONT FENDER ATTACHMENT PARTS X NN	1	\$	55.00	
32	FRONT FENDER CLOSING ELEMENT - LH / RH X NN	2	\$	166.00	
33	FRONT FENDER BRACKET - LH / RH X NN	2	\$	82.00	
34	FRONT FENDER RIVET X NN	11	\$	42.00	
35	FRONT FENDER BRACE - LH / RH X NN	2	\$	264.00	
36	FRONT WHEEL HOUSING LINER - LH / RH X NN	2	\$	598.00	
37	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS X NN		\$	176.00	
38	FRONT WHEEL SPOILER - LH / RH X NN	2	\$	164.00	
39	BONNET / DD	1	\$	3,491.00	2792.80
40	BONNET ATTACHMENT PARTS X NN	1	\$	128.00	
SUB TOTAL SPARE PARTS		:	\$	9,631.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 173 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	BONNET HINGE - LH / RH X NN	2	\$	932.00	
42	BONNET IMPACT PROTECTION - CENTER / LH / RH X NR	3	\$	93.00	73.20
43	BONNET SOUND ABSORBER X CK1	1	\$	382.00	305.60
44	BONNET BOWDEN CABLE - CENTER X TN	1	\$	64.00	50.56
45	BONNET RELEASE LEVER X NN	1	\$	15.00	
46	BONNET BOWDEN CABLE - CENTER X BT	1	\$	64.00	50.56
47	BONNET BOWDEN CABLE COVER X NN	1	\$	11.00	
48	BONNET STRIKER - LH / RH X BT	2	\$	112.00	89.12
49	BONNET LOCK X BT	2	\$	455.00	364.00
50	FRONT FENDER TOP LEDGE COVER - LH / RH X NN	2	\$	80.00	
51	FRONT FENDER INNER LEDGE COVER - LH / RH X BRO2	2	\$	98.00	77.28
52	HEADLIGHT - LH / RH X BR	1	\$	16,344.00	6537.60
53	HEADLIGHT HOSE X NN	1	\$	42.00	
54	HEADLIGHT COMPENSATING PIECE X NR	2	\$	90.00	71.04
55	HEADLIGHT COMPENSATING PIECE X NN	1	\$	47.00	
56	LIFT CYLINDER BRACKET - RH X NN	1	\$	17.00	
57	LIFT CYLINDER - LH / RH X NN	2	\$	434.00	
58	LIFT CYLINDER CORRUGATED PIPE X NN	1	\$	107.00	
59	LOCK CARRIER X BR	1	\$	1,478.00	901.60
60	COOLANT REGULATOR SUPPORT - LH / RH X NN	2	\$	85.00	
SUB TOTAL SPARE PARTS			:	\$	20,950.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 173 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	AIR COOLER CHARGE X NN	1	\$ 654.00	
62	A/C CONDENSER / BT	1	\$ 683.00	546.00
63	A/C CONDENSER REFRIGERANT LINE X NN	1	\$ 186.00	
64	A/C CONDENSER REFRIGERANT LINE X NN	1	\$ 381.00	
65	A/C CONDENSER REFRIGERANT LINE X NN	1	\$ 277.00	
66	OUTSIDE TEMPERATURE SENSOR BRACKET 2/ NEC	1	\$ 21.00	16.32
67	RADIATOR COOLANT / MC (P/M)	1	\$ 699.00	558.80
68	RADIATOR COOLANT FAN RING / BR	1	\$ 277.00	221.20
69	RADIATOR FAN CONTROL UNIT X NN	1	\$ 2,012.00	
70	RADIATOR AIR GUIDE - LH / RH CRH - BR / 2/	2	\$ 72.00	56.80
71	RADIATOR AIR GUIDE - LH / RH CRH - BR / 2/	2	\$ 38.00	29.28
72	RADIATOR AIR GUIDE - UPPER / CRH	1	\$ 19.00	14.64
73	RADIATOR AIR GUIDE - LOWER X NN	1	\$ 25.00	
74	READY- MIX COOLANT / MC	6	\$ 297.00	237.12
75	INTAKE AIR DUCT - RH / BR	1	\$ 25.00	19.68
76	INTAKE AIR DUCT AIR GUIDE / BR	1	\$ 61.00	48.48
77	INTAKE AIR DUCT HOSE / BR	1	\$ 110.00	88.00
78	AIR FILTER X NN	1	\$ 418.00	
79	FRONT FENDER TRIM - LH / RH / MC	1/2	\$ 342.00	136.40
80	FRONT DOOR TRIM - LH / RH / MC	1/2	\$ 342.00	136.40
SUB TOTAL SPARE PARTS		:	\$ 6,939.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAIR@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 173 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	FRONT WINDOW SLOT SEAL TRIM STRIP - LH / RH X NN	2	\$ 892.00	
82	FRONT ROOF MOLDING - LH / RH / IN 12	12	\$ 1,412.00	564.80
83	FRONT WATER DEFLECTOR STRIP - LH / RH X NN	2	\$ 150.00	
84	FRONT FENDER PROTECTION FILM - LH / RH X NN	2	\$ 40.00	
85	FRONT NO PLATE / 17	S/N	\$ 150.00	150.00
86	SUNDRIES 2 Nec		\$ 500.00	43.44
TOTAL SPARE PARTS		:	\$ 50,437.00	
TOTAL LABOUR CHARGES		:	\$ 19,724.00	
GRAND TOTAL		:	\$ 70,161.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

ster (LXX)
5/9/12, 4:00p

OD-M AL
EXCII-?
P/P
LJ BL y
11 y s

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT