



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE)SINGAPORE 417883 ON BEHALF OF KIAN DE SERVICERS			Ref: CS/TP22008714/Uqy3e2 Date: 19/09/2022 Code: TP149	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	SLH 8856K	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	06/09/2022	
2. Vehicle Particulars & Condition				
	Make & Model	HONDA HRV DX (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JHMRU1810GX201090	Colour	WHITE
	Odometer	424731 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	MICHELIN	6 mm
	L/H Front Tyre	215/60 R16	MICHELIN	6 mm
	R/H Rear Tyre	215/60 R16	MICHELIN	6 mm
	L/H Rear Tyre	215/60 R16	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	16/08/2022	Inspection Date	06/09/2022
	Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	