



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/09/2022

User ID : JeongCH

Section A - Accident Details			
Registration Number	SG5809P		
Case Reference Number	BUS/04/22/7033		
Registration Date	6/6/2017		
Company Type	SMRT Buses Ltd		
Make	MAN		
Model	A95 MAN E6		
Name of Driver	Muhammad Noh Bin Sukor		
Type of Accident	Side Swipe		
Accident Date and Time	4/22/2022 1:41 PM		
Accident Reported Date and Time	4/22/2022 2:45 PM		
Is Surveyor Required?	No		
Survey by			
Vehicle is Towed Back?	No		
Towed Back Date and Time			
Replacement Vehicle issued?	No		
Job Card Number			
Special Instruction to ARC,if any	SG5809P - Right front bumper scratched SKU2472S (TP) - INSURED WITH CHINA TAIPING		
Prepared Date and Time	9/6/2022 11:03 AM		
Chassis Number	WMAA95ZZ5G7003456		
Mileage			
Work Shop			
Repair Completion Date and Time			

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$616.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,411.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	2.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	06/09/2022 11:07 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/09/2022

User ID : JeongCH

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope				Quotation from AR				Adjusted by Surveyor, if applicable	
TO REPAIR RH FRONT PORTION				\$795.00					
Total Labour				\$795.00					
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS				\$616.00					
Total Spray Painting & Panel Beating				\$616.00					
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6013418	Body	155-2-2-009002	O/S FRP FRONT HEADLAMP COVER	1.00	\$975.00	100.00	\$0.00	Repair	
Total					\$975.00		\$0.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									