



凱摩哆服務 KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。
Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date: 05/09/2022

Attn: The Motor Claims Department
Your Insured Vehicle - SKW 349 T

HL Assurance Singapore

11 Keppel Road #11-01, ABI Plaza, Singapore 089057
H +65 6702 0202 | F +65 6221 3782
claims@hla.com.sg | www.hla.com.sg

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WITHOUT PREJUDICE

Dear Sir / Madam

Estimated Cost of repair for Vehicle Toyota Wish SMN 8384 L And SKW 349 T on 02/09/2022 at 18:00.

1pc	Rear Boot Cover	1570		\$	1,061.30	bt
1pc	Rear Boot Cover Logo			\$	75.10	nel
1pc	Rear Boot Cover Moulding			\$	110.20	xun
1pc	Rear Windscreen Glass Seal			\$	55.10	nel
1pc	Rear Boot Cover Inner Lock	395		\$	359.40	bt
1pc	Rear Boot Cover Inner Rubber	338.20		\$	399.15	int
2pcs	Rear Lamp	@430	2pcs X \$401.35	\$	802.70	LH-RH x
1pc	Rear Panel			\$	519.40	Rx
1pc	Rear Panel Inner Garnish	285.60		\$	201.40	de
1pc	Rear Bumper	590		\$	695.40	de
10pcs	Rear Bumper Clips			\$	150.00	50 nel
2pcs	Rear Bumper Side Retainer	60	2pcs x \$110.35	\$	220.70	LH de - RH x
2pcs	Rear Bumper Reflector		2pcs x \$66.10	\$	132.20	xun
1pc	Rear Lamp Lower bracket LH			\$	56.10	xun
				\$	4,838.15	
				-\$	1,209.54	
				\$	3,628.61	
1pc	Reverse Sensor			\$	380.00	200 nel
1pc	Windscreen Glass Sealant			\$	70.00	50 nel
				\$	950.00	600
				\$	1,100.00	700
				\$	120.00	office
				\$	150.00	BoH nel
				\$	120.00	30
				\$	100.00	30
				\$	6,618.61	

To dismantl & replace damage parts, panel beat where necessary

To putty, apply primer & spray paint on the affected portion.

To dismantl & refix rear windscreen glass

To spray puff cost

To remove reverse sensor.

To check wiring functions.

Taufan 17495749/6256356P
WP' 6/9/2022
L/S Resurvey after repair
A. Taufan@lkhauto.com
5 days