



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: KHOR SAW THENG			Ref: CS/ASM22008723/Gcy3e2 Date: 03/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHF 610M	Veh. Inspected	FBJ 2992Y
	Policy No.	VFX/P2413997	Coverage (\$)	0.00
	Claim No.	S2M049JI	Excess (\$)	0.00
	Assign From	KHOR SAW THENG	Assign Date	05/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA ADV 150	c.c	149
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	MH1KF6116LK030138	Colour	WHITE
	Odometer	29919 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	110/70-14	PIRELLI	5 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	130/70-13	PIRELLI	5 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/08/2022	Inspection Date	06/09/2022
	Survey held at	GUSTO BROZ PTE LTD 25 KAKI BUKIT ROAD 4, #01-35, SYNERGY @ KB, SINGAPORE 417800		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	