



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: LOW GARNET			Ref: CS/ASM22008726/Svy3m4 Date: 19/09/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SML 1931P	Veh. Inspected	SBH 7610C
	Policy No.	P2286691	Coverage (\$)	0.00
	Claim No.	S2M04AA7	Excess (\$)	0.00
	Assign From	LOW GARNET	Assign Date	05/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA STARLET XL	c.c	1290
	Engine No.	HIDDEN	Year of Reg.	1989
	Chassis No.	EP700171107	Colour	BLACK
	Odometer	581667 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/50 R15	GENERAL	6 mm
	L/H Front Tyre	195/50 R15	GENERAL	6 mm
	R/H Rear Tyre	195/50 R15	GENERAL	7 mm
	L/H Rear Tyre	195/50 R15	GENERAL	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/08/2022	Inspection Date	06/09/2022
	Survey held at	H S AUTOMOTIVE SERVICES 2 KAKI BUKIT AVE 2 #01-15 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	