



HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

INDEPENDENT SURVEYOR

DIRECT SETTLEMENT

Vehicle No :

SBA 7610C

lake/Model :

Y0Y0YA STARLET

CHASSIS NO :

EP700171107

WORK SHOP REPAIRER ESTIMATE

Date:

06/09/22

Estimate cost of repair to the above mentioned

MARKING

UNIT \$

AMOUNT (\$\$)

NO. QTY List Items

Final price

Final marking

1	1	REAR BUMPER ((rack) Dent	/	\$ -	\$ 545 -
2	2	REAR BUMPER RETAINER (NN)	?	\$ -	\$ NA -
3	1	REAR BUMPER M/PLAYZ LAMP crack	/	\$ -	\$ 187.30
4	2	REAR BUMPER REINFORCEMENT (DENT)	?	\$ -	\$ 450.60
5	1	REAR END PANEL Dent		\$ -	\$ 607.34
6	1	REAR END PANEL TOP GARK/18TH. Rack	/	\$ -	\$ 129.09
7	1	REAR END PANEL WHEY4ER STRID. turn		\$ 150 -	\$ 217.50
8				\$ -	\$ -
9		PANEL BRAY	/	\$ 400 -	\$ 800 -
10				\$ -	\$ -
11		RESPRAY PANEL	/	\$ 400 -	\$ 800 -
12				\$ -	\$ -
13		RUST PROOF	X	\$ X -	\$ 100 -
14				\$ -	\$ 3836.83
15				\$ -	\$ -
16				\$ -	\$ -
17				\$ -	\$ -
18				\$ -	\$ -
19				\$ -	\$ -
20				\$ -	\$ -

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Part Price 1461

25% 365

Total part 1096

Total : 1516

≈ 1500

REMARKS:

NO OF DAYS:

3 days 4/5 After repair pic

AGREED FIGURE/LUMP SUM:

\$ -

SURVEYOR NAME

mohamed Irfan - LKK

CONTACT:

90047659

EMAIL ADD: