



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD

10 MARINA BOULEVARD
#48-01 MARINA BAY FINANCIAL CENTRE TOWER
2SINGAPORE 018983

ATTN: KHOR SAW THENG

Ref: CS3/ASM22008727/Scy3e2

Date: 06/02/2023

Code: HSB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1041P	Veh. Inspected	YP 6034H
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S2M046SL	Excess (\$)	0.00
Assign From	KHOR SAW THENG	Assign Date	05/09/2022

2. Vehicle Particulars & Condition

Make & Model	ISUZU FSR34SUQCC	c.c	7790
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JALFSR347H7000011	Colour	WHITE
Odometer	180447 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	265/70 R19.5	INDFORCE	6 mm
L/H Front Tyre	265/70 R19.5	INDFORCE	6 mm
R/H Rear Tyre	265/70 R19.5	INDFORCE	7 mm
L/H Rear Tyre	265/70 R19.5	INDFORCE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/07/2022	Inspection Date	06/09/2022
Survey held at	H S AUTOMOTIVE SERVICES 2 KAKI BUKIT AVE 2 #01-15 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------