



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SFU281Z

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT  
6 RAFFLES QUAY  
#21-00  
SINGAPORE 048580  
65073848

### Vehicle & Document Information

WIP No **59380**  
Reg No/Reg Date **SFU281Z / 05/09/2019**  
Date In/Mileage **/ 0**  
Chassis No **WDD2130802A682627X**  
Engine No **26492080006380**  
Make/Model **MB/E 200 SEDAN AVANTGARDE**  
Colour/Trim **028 890 Cavansite B/ 042 214 Leather Nut**

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	05/09/2022/ 11:41	AQ	305 / Alan Quek Ai Lun
Description of Goods / Services				
	Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : 1900156632 // 03-09-2022  
DRIVE IN: 05-09-2022 // TP CAR NO: SLM2393S (MS FIRST CAPITAL INSURANCE)  
DATE IN/DATE SURVEY:  
BY/AUTHORIZED ON :

A BPILAB

USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO  
STANDARD SETTINGS.NETT

S BPNSUB

SUPPLY & TRANSFER 1PC FRONT LEFT RIM  
PURCHASE ORDER NO:

A BPILAB

INSPECT & CONDUCT WHEEL ALIGNMENT.NETT

A BPILAB

REMOVE & REPAIR FRONT BUMPER AND FRONT LEFT FENDER

A BPIRES

RESPRAY FRONT BUMPER & FRONT LEFT FENDER

M LH/F DISC WHEEL

0.10 380.00

60.00

540.00

1440.00

1800.00

1.00 690.65 00.00 690.65

**Alan Quek**  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272  
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 4,910.65  
7% GST on 4910.65 343.75

Authorized signatory and company stamp

Total Payable 5,254.40

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg