

TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : BUKIT TIMAH  
CONTACT NO : 4694091  
REFERENCE : INS/IC/ZHR/0252/2022  
DATE : 03-SEP-2022

ALLIANZ INSURANCE SINGAPORE PTE LTD  
79 ROBINSON ROAD #09-01

S(068897)  
TEL : 63954779/67143369  
FAX : 63953768  
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : ONG LEE LIN  
ADDRESS : 12A CHESTNUT CRESCENT

S(679367)  
TELEPHONE NO : 67605121/90669793

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : TP-Q9L  
VEHICLE NO : SKS642S  
MODEL CODE : BDTARCZBI7EWA----K19  
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT) MY2019  
ENGINE NO : HR16951788C  
CHASSIS NO : MNTBBAB17Z0037334  
MILEAGE : 1 KM  
DATE IN : 03/09/2022  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : MUHAMMAD ZUHRI  
ACCIDENT DATE : 31/08/2022

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKS642S

| S/NO                 | JOB CODE | NATURE OF JOB                                           | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATION |
|----------------------|----------|---------------------------------------------------------|----------------------|------------------------------|
| 1                    | FHI      | R/INSTALL FR H/LAMP ASSIST TO REPAIR                    | 48.00                |                              |
| 2                    | RPI      | PERFORM RUST PROOFING & TREATMENT FOR AFFECTED<br>PANEL | 120.00               |                              |
| 3                    | ZZ/001   | REPAIR UPP PANEL & RENEW FR BUMPER                      | 585.00               |                              |
| 4                    | ZZ/002   | S/PAINT FR PANEL & FR BUMPER                            | 500.00               |                              |
| TOTAL LABOUR CHARGES |          |                                                         | 1253.00              |                              |

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKS642S

| S/NO                                                  | PARTS DESCRIPTION   | PARTS NUMBER | DAMAGED PARTS & PRICES |      |        | REMARKS |
|-------------------------------------------------------|---------------------|--------------|------------------------|------|--------|---------|
|                                                       |                     |              | NETT                   | LIST | S/NETT |         |
| 1                                                     | FRT LICENCE PLATE   | FLP          |                        |      | 60.00  |         |
| 2                                                     | SUNDRIES            | NPN          |                        |      | 20.00  |         |
| 3                                                     | BRKT FR BUMPER      | 62224-3SN5A  | 12.00                  |      |        |         |
| 4                                                     | ABSORBER ENERGY     | 62090-3SN5A  |                        |      | 180.00 |         |
| 5                                                     | FINISHER FRT BUMPER | 62256-3SN5A  | 45.00                  |      |        |         |
| 6                                                     | LAMP FOG RH         | 26150-8990A  |                        |      | 347.00 |         |
| 7                                                     | GRILLE              | 62310-3SN1A  | 320.00                 |      |        |         |
| 8                                                     | GRILLE ASSY FR LWR  | 62254-3SN5A  |                        |      | 95.00  |         |
| 9                                                     | FACE-FR BUMPER      | 62022-3SN5H  | 680.00                 |      |        |         |
| 10                                                    | LAMP ASSY HEAD RH   | 26010-3SN7A  | 680.00                 |      |        |         |
| 11                                                    | CLIP(\$1.5X10)      | 01553-09321  | 15.00                  |      |        |         |
| 12                                                    | GROMMET(\$1.4X2)    | 01281-01431  | 2.80                   |      |        |         |
| 13                                                    | CLIP(\$1.3X10)      | 01553-10501  | 14.00                  |      |        |         |
| SUB TOTAL                                             |                     |              | 1768.80                | 0.00 | 702.00 |         |
| LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%) |                     |              | 353.76                 | 0.00 | 0.00   |         |
| GRAND TOTAL                                           |                     |              | 1415.04                | 0.00 | 702.00 |         |
| OVERALL TOTAL                                         |                     |              | 2117.04                |      |        |         |

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKS642S

-----

|                           |           |
|---------------------------|-----------|
| TOTAL LABOUR CHARGES      | 1253.00   |
| TOTAL SPARE PARTS CHARGES | 2117.04   |
| -----                     |           |
| GRAND TOTAL               | 3370.04 * |
| -----                     |           |

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

-----

|                 |   |      |
|-----------------|---|------|
| NAME            | : |      |
| SURVEYED DATE   | : |      |
| AUTHORIZED DATE | : |      |
| EXCESS CLAUSE   | : | 0.00 |
| LIABILITY       | : | 0.00 |
| REMARKS         | : |      |

PLS NOTE : This estimate is based on visual inspection of the  
affected vehicle. Should we require further labour  
charges & spare parts in the process of repairs, we  
shall inform you accordingly.