

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 12 Oct 2022

Preliminary Advice

Insured : SMZ1022P
Vehicle No
TP Vehicle : FBR507L Accident Date : 31/08/2022
No
Make : HONDA ADV150 Assignment Date : 06/09/2022
Date of : 07/09/2022 Est. Duration of : 4
Inspection Repair
Inspection At : EROFIA MOTOR TRADING PTE LTD - (KAKI BUKIT) (HQ)
1 KAKI BUKIT AVENUE 6, #02-62 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,430.10
Revised Amount	:S\$	2,640.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,640.40
Lump Sum Repair	:S\$	2,100.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$

Margin for Repair

:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.