



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL  
64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Ref: CS3/III22008734/y3

Date: 06/09/2022

Code: III2

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLT 4120M	Veh. Inspected	SLE 7186H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	BHUVANESWARI	Assign Date	06/09/2022

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	31/08/2022	Inspection Date	
Survey held at	KING'S AUTO REPAIR & SERVICE PTE LTD 176 SIN MING DRIVE, #02-10, SIN MING AUTOCARE, SINGAPORE 575721		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.