

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 04/09/2022

07/10/2022

TP 1st Cap.
Veron.

Estimated repair cost for vehicle no: YQ10K MITSUBISHI CANTER FEB21ER4SDEN (CBU)

CHASSIS: FEB21EA30011 (2018)

S/N	Qty	Items	1010.34	Amount	
1	1	FRONT BUMPER <i>Dehnd</i>	\$1,010.34	\$1,010.34	✓
2	1	FRONT BUMPER BRACKET LH <i>xtm</i>	\$203.13	\$203.13	✓
3	1	FRONT BUMPER SIDE GUIDE LH <i>at</i>	\$353.71	\$353.71	✓
4	1	LH FRONT HEADLAMP <i>Amled</i>	\$501.42	\$501.42	✓
5	1	LH FRONT HEDALAMP LOWER RUBBER <i>Not new</i>	\$25.03	\$25.03	X
6	1	LH FRONT SIGNAL LAMP <i>Amled</i>	\$266.36	\$266.36	✓
7	1	LH FRONT LAMP COVER <i>Amled</i>	\$230.34	\$230.40	✓
8	1	LH FRONT CORNER PANEL <i>Dehnd</i>	\$524.54	\$524.54	408
9	1	LH FRONT DOOR <i>Dented</i>	\$2,071.55	\$2,071.55	1850
10	2	LH FRONT DOOR HINGE <i>zap</i>	\$168.25	\$336.50	X
11	1	LH FRONT DOOR CHECKER <i>ra</i>	\$86.45	\$86.45	X
12	1	LH FRONT DOOR AIR VENT <i>xtm</i>	\$50.31	\$50.31	X
13	1	LH FRONT DOOR STICKER EMBLEM BLUETEC <i>ra</i>	\$47.12	\$47.12	✓
14	1	LH FRONT DOOR OUTER GARNISH <i>xtm</i>	\$124.00	\$124.00	X
15	1	LH FRONT MIRROR (SQAURE) <i>at</i>	\$215.00	\$215.00	✓
16	1	LH FRONT MIIROR (ROUND) <i>xtm</i>	\$197.00	\$197.00	X
17	1	LH FRONT MIRROR ARM <i>Bent</i>	\$408.00	\$408.00	✓
18	1	LH FRONT STEP GARNISH <i>at</i>	\$622.40	\$622.40	325

25%

TOTAL :	\$7,273.26
LESS 10 %	\$727.33
SUB-TOTAL :	\$6,545.93

5400.35

4050.26

YQ10K MITSUBISHI CANTER

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	FRONT HEADLAMP CLIPS	\$40.00	\$40.00 10
2	1	FRONT SIGNAL LAMP CLIPS	\$30.00	\$30.00 10
3	1	FRONT CORNER PANEL CLIPS	\$50.00	\$50.00 20
4	1	LH FRONT TYRE	\$320.00	\$320.00 1
5	1	LH FRONT TYRE RIM	\$550.00	\$550.00 1
6	1	LH FRONT DOOR COMPANY STICKER	\$500.00	\$500.00 200
7	1	LH FRONT DOOR INNER TRIM BOARD CLIPS	\$80.00	\$80.00 1

240 TOTAL: \$1,570.00

TOTAL PARTS : \$8,115.93

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 LABOUR FOR REMOVE & TRANSFER ALL LH FRONT DOOR FITTING
- 5 TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS

350 \$1,500.00 ~~500~~ 500
 \$1,200.00 ~~500~~
 \$80.00 ~~30~~
 \$200.00 ~~80~~
 \$200.00 ~~40~~

Subtotal : \$3,180.00

Total:- \$11,295.93

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Supplementary: 635.62
 total: 6275.88
 L/S: SK

SK
 05 Days

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

07/10/2022

01-43

Singapore 417883

Accident date : 04/09/2022

Estimated repair cost for vehicle no: YQ10K MITSUBISHI CANTER FEB21ER4SDEN (CBU)

CHASSIS: FEB21EA30011 (2018)

S/N	Qty	Items	1010.34	Amount
1	1	FRONT GRILLE <i>cracked</i>	\$762.10	\$762.10
2	1	FRONT GRILLE LOGO <i>flu</i>	\$85.40	\$85.40

TOTAL : \$847.50

25% LESS 10 % \$84.75

SUB-TOTAL : \$762.75

847.50

635.62