

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22008743/UCY3E2**Date:** 28/09/2022**REFERENCE**

Insured/Claimant:	LEE ZHISHENG	Policy No:	MPC22B00007900	
Date of Loss:	03/09/2022	Nature of Claim:	OD	Claim No: DMPC2200396H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ3954U	Engine No:	CDN244692
Make & Model:	AUDI A5, 2.0 (A)	Chassis No:	WAUZZZ8T1CA018891
Reg. Date:	27/03/2013 (Man. Year: 2012)	Odometer:	74758 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$41,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/30Z R20	Rear Tyre Size:	275/30Z R20
Front Left Side:	Pirelli 2 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 2 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	06/09/2022 Present Location:	SME Motor Pte Ltd (Kaki Bukit)
Date Inspected:	07/09/2022 Inspected At:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	0.0 days	

Adjuster: MARCUS CHUA**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$41,000.00
OMV :	\$67,716.00
PARF Rebate (1) :	\$31,358.00
Quota Premium Paid :	\$92,667.00
COE Rebate (2) :	\$ 5,106.00
Total Rebate (1) + (2) = :	\$36,464.00

The total amount incurred will be Market Value \$41,000.00 minus Total Rebate \$36,464.00 = \$4,536.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Sep 2022)	
Parts:	N/A	AUDI A5 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKJ3954U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >