

J&M CONSULTANCY PTE LTD

11 Changi South Lane #02-08
ONN WAH BUILDING Singapore 486154
Company Reg No: 202125502E
Tel: 6214-0474 Fax: 6384-5205

VEHICLE INSPECTION REPORT

To: STARK HOLDINGS INN BIKE LEASING PTE LTD

Date : 12 August 2022

C/o: A-Tec Automotive Pte Ltd
8 Kaki Bukit Avenue 4
#04-20 Premier @ Kaki Bukit, Singapore 415875

Our ref : ATEC/08/0019/JM

Accident Date : 15 March 2022

Type of Survey : Third party

Inspection Date : 16 March 2022

Repairer Name : A-Tec Automotive Pte Ltd

8 Kaki Bukit Avenue 4

#04-20 Premier @ Kaki Bukit, Singapore 415875

PARTICULARS OF VEHICLE

Registration No : SLP 8814 P

Year / Capacity : 2017 / 1798 cc

Make / Model : Toyota / Prius Plus Hybrid

Colour : Silver

Chassis No : JTDKB3FU103560476

Mileage : 214,003 km

Engine No : 2ZRS053712

CONDITION OF TYRES

	Make	Size	Thread Balance
Front Nearside :	Aplus	195/65/ R15	80%
Front Offside :	Aplus	195/65/ R15	80%
Rear Nearside :	Aplus	195/65/ R15	80%
Rear Offside :	Aplus	195/65/ R15	80%

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear bumper portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 47 copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

Vehicle Registration No: SLP 8814 P

Our Ref No: ATEC/08/0019/JM

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

Under normal circumstances, the repair period would be about **7 (Seven)** working days.

Qty	Description	Condition	Repairer's Estimate	Revised Amount
-----	-------------	-----------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Rear bumper assy (1 set)	Warped	\$ 1,500.00	\$ 1,500.00	654 ✓
1	Rear bumper bracket (1 set)	Warped/Necessary	\$ 450.00	\$ 450.00	X nn
1	Rear bumper retainer (1 set)	Warped/Necessary	\$ 480.00	\$ 480.00	224 ✓
1	Rear bumper reinforcement bar	Bent	\$ 680.00	\$ 680.00	360 ✓
1	Rear bumper lower garnish	Warped	\$ 550.00	\$ 550.00	503 ✓
1	Rear bumper reflector (1 set)	Cracked	\$ 475.00	\$ 475.00	X nn
1	Rear bumper taillamp LH	Cracked	\$ 1,650.00	\$ 1,650.00	X nn
1	Rear bumper taillamp RH	Cracked	\$ 1,650.00	\$ 1,650.00	559 ✓
1	Rear taillamp LH	Cracked	\$ 1,850.00	\$ 1,850.00	X nn
1	Rear taillamp RH	Cracked	\$ 1,850.00	\$ 1,850.00	634 ✓
1	Rear tailgate assy	Repair	\$ 1,600.00	\$ -	X R
1	Rear tailgate inner garnish	Warped	\$ 520.00	\$ 520.00	X nn
1	Rear tailgate lock latch	Bent	\$ 300.00	\$ 300.00	X nn
1	Rear tailgate weatherstripe	Warped/Necessary	\$ 440.00	\$ 440.00	X nn
1	Rear exhaust pipe muffler	Bent	\$ 730.00	\$ 730.00	X nn
1	Rear end panel	Warped	\$ 990.00	\$ 990.00	X R
1	Rear end panel inner	Warped	\$ 950.00	\$ 950.00	X nn
			\$ 12,415.00	\$ 15,065.00	2934
	Less 25%		\$ 4,166.25	\$ 3,766.25	-25%
			\$ 16,665.00	\$ 11,298.75	2200.50

SPECIAL NETT ITEMS

1	Rear bumper clip (1 set)	Necessary	\$ 100.00	\$ 100.00	30
1	Rear bumper reverse sensor (1 set)	Malfunction	\$ 650.00	\$ 650.00	200
1	Rear end panel sealant	Necessary	\$ 120.00	\$ 120.00	X nn
1	Rear reverse camera (1 set)	Malfunction	\$ 850.00	\$ 850.00	X nn
			\$ 1,720.00	\$ 1,720.00	
	Total parts		\$ 14,218.75	\$ 13,018.75	230

