



TONG LUCK AUTO PTE LTD
 160 SIN MING DRIVE #07-01/06 SIN MING AUTO CITY, SINGAPORE 575722
 Tel: 6250 0088 Fax: 6250 5645
 Email: operation@tlauc.com.sg
 GST No: 201700521W UEN No: 201700521W

M/S : RMG RENT-A-CAR PTE LTD
 10 JALAN KILANG #01-01/02
 BUKIT MERAH ENTERPRISE CENTRE,
 SINGAPORE 159410

TEL : 6235 1311 FAX : 6235 5256
 ATTN :

YOUR REF NO : SLQ2309R
 CLAIM TYPE : THIRD PARTY
 TP INS. CO. :
 ACCIDENT DATE : 01/09/2022
 TP VEH REG NO : SLQ2309R

PAGE: 2

ESTIMATE
 NO : QUOT20209-000006(00)
 DATE : 05/09/2022
 POLICY NO : SD22V05556VPF7/R09
 VEH REG NO : **SJN8488G**
 MAKE/MODEL : TOYOTA CAMRY 4-DOOR
 SEDAN (AUTO) 2.0
 CHASSIS NO : MR2BN3HK50400545
 ENGINE NO : 6ARP643598
 REG. DATE : 2019

Estimate Repair Cost to Vehicle No : SJN8488G

Description	Quantity	Unit Price	Amount
		S\$	S\$
33 Bootlid camera	1	680.20	680.20
34 Bootlid insulator	1	633.95	633.95
35 Bootlid insulator clips	15	12.90	193.50
36 Rear number plate lamp - RH / LH	2	115.85	231.70
37 Rear end panel	1	651.90	651.90
38 Rear end panel top garnish	1	299.60	299.60
39 Rear end panel top garnish clips	1	44.00	44.00
40 Taillamp assy - RH / LH	8	5.50	44.00
41 Taillamp lower bracket - RH / LH	2	758.90	1,517.80
42 Rear fender - LH	2	129.60	259.20
43 Rear fender inner shield - LH	1	1,078.85	1,078.85
44 Rear fender inner shield clips - LH	1	291.60	291.60
45 Rear fender inner trim - RH / LH	20	12.90	258.00
46 Rear bumper	2	396.50	793.00
47 Rear bumper retainer - RH / LH	1	619.60	619.60
48 Rear bumper reinforcement	2	121.60	243.20
49 Rear bumper reverse sensor	1	319.60	319.60
50 Rear bumper spoiler	4	469.00	1,876.00
51 Rear bumper reflector - RH / LH	1	398.90	398.90
52 Rear bumper towing cover	2	91.80	183.60
53 Rear bumper air-duct - RH / LH	1	38.90	38.90
54 Rear exhaust silencer	2	69.60	139.20
	1	886.90	886.90
			33,732.85
		Less 25%	8,415.72
			25,317.13
SPECIAL NET			
55 Front number plate with casing	1	40.00	40.00
56 Rear number plate with casing	1	40.00	40.00
			80.00
LABOUR			
57 To remove and refit front and rear bumper sensor	1	200.00	200.00
58 To check and rectify wiring system (Front and Rear)	1	160.00	160.00
59 To remove and refit rear exhaust silencer	1	180.00	180.00

SPECIAL NET

- 55 Front number plate with casing
- 56 Rear number plate with casing

LABOUR

- 57 To remove and refit front and rear bumper sensor
- 58 To check and rectify wiring system (Front and Rear)
- 59 To remove and refit rear exhaust silencer

TOTAL

Aspire 3
 DDR4
 Faster memory speed
 Precision touchpad
 Faster wireless
 Gigabit Ethernet
 100Mbps
 802.11ac
 A314-32-C6Z5
 Inside Celeron® processor M420
 Inside UHD Graphics
 1.32GHz SMD



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTO CITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545
 Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 3

M/S : RMG RENT-A-CAR PTE LTD
 10, JALAN KILANG #01-01/02
 BUKIT MERAH ENTERPRISE CENTRE,
 SINGAPORE 159410
 TEL : 6235 1311 FAX : 6235 5256
 ATTN :
 YOUR REF NO : SLQ2309R
 CLAIM TYPE : THIRD PARTY
 TP INS. CO.
 ACCIDENT DATE : 01/09/2022
 TP VEH REG NO : SLQ2309R

ESTIMATE
 NO : QUOT202209-000006(00)
 DATE : 05/09/2022
 POLICY NO : SD22V05556/VPIR09
 VEH REG NO : SJN8488G
 MAKE/MODEL : TOYOTA CAMRY 4-DOOR
 SEDAN (AUTO) 2.0
 CHASSIS NO : MR2BN3HK904005455
 ENGINE NO : 6ARP543598
 REG. DATE : 2019

Estimate Repair Cost to Vehicle No : SJN8488G

Description	Quantity	Unit Price	Amount
		S\$	S\$
60 To panel beat and straighten front & rear chassis frame, rear floorboard panel, to cut and weld rear end panel, LH rear fender, rear spare tyre well, including replacement of parts and align where necessary, to refit and adjust the same.	1	2,000.00	2,000.00
61 To putty and spray paint on front affected areas	1	2,500.00	2,500.00
62 To apply rust proofing on front replaced and repaired panels	1	220.00	220.00
63 To remove and refit rear camera	1	180.00	180.00
			5,440.00

1800
1600
900
500

TOTAL **S\$ 30,837.13**
 ADD GST @ 7% 2,158.60
 GRAND TOTAL **S\$ 32,995.73**

SINGAPORE DOLLAR THIRTY-TWO THOUSAND NINE HUNDRED NINETY-FIVE AND CENTS SEVENTY-THREE ONLY

stuff
To spray Rear Spare Tyre. Saw

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

Interview to
 Tech Invs (S)



Faster

Precision

Faster

Gigabit

**TONG LUCK AUTO PTE LTD**

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

M/S : RMG RENT-A-CAR PTE LTD

10 JALAN KILANG #01-0102
BUKIT MERAH ENTERPRISE CENTRE,
SINGAPORE 159410

TEL : 6235 1311

FAX : 6235 5256

ATTN :

YOUR REF NO : SLO2309R

CLAIM TYPE : THIRD PARTY

TP INS. CO. : MSIG INSURANCE (SINGAPORE) PTE LTD

ACCIDENT DATE : 01/09/2022

TP VEH REG NO : SLO2309R

PAGE: 1

ESTIMATENO : QUOT202209-0000006(00)
DATE : 05/09/2022
POLICY NO : SD22V055566VPZR09
VEH REG NO : SJK8488G
MAKE/MODEL : TOYOTA CAMRY 4-DOOR
SEDAN (AUTO) 2.0
CHASSIS NO : MR2BN3HK504005455
ENGINE NC : 6ARF643598
REG. DATE : 2019**Estimate Repair Cost to Vehicle No : SJK8488G**

Description	Quantity	Unit Price	Amount
		SG	SG
SUPPLEMENTARY			
LIST PRICE			
1 Air-con condenser →	1	2,005.95	2,005.95
2 Radiator Assy →	1	2,363.10	2,363.10
3 Radiator air- guide R/H/LH	2	93.70	187.40
4 Radiator guide	1	93.70	93.70
5 Front bumper sponge	1	103.90	103.90
6 Rear bumper sensor seal	6	12.00	72.00
7 Rear well stopper	1	158.30	158.30
8 Rear spare tyre screw	1	155.20	155.20
9 Rear exhaust heating seal (Top)	1	181.90	181.90
10 Rear end chrome	1	175.20	175.20
11 Rear spare tyre panel coating	1	68.40	68.40
12 Rear spare tyre box	1	319.60	319.60
		Less 25%	5,884.65
			1,471.14
			4,413.51
			150.00
			150.00
			300.00
		TOTAL	SG 4,713.51
		ADD GST @ 7%	329.95
		GRAND TOTAL	SG 5,043.46

LABOUR

- 13 To remove and refit aircon condenser and top up 134 gas
14 To remove and refit radiator and refill coolant

SINGAPORE DOLLAR FIVE THOUSAND FORTY-THREE AND CENTS FORTY-SIX ONLY

J.P = \$ 25,629.89 @ 18 days

use give extra 2 days for repairs

Mont's

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE