

ASS. REC. BY:

REF: MSG/ 220087501kv

Kennerth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Tony Luke of \_\_\_\_\_

Insured: SLU 7437A

Policy No. 30001962127

Claims No. 283880


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$122k

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 16 days Res.: Yes or No

Lum Sum: 1-13.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: STN 8488G Yr Regn: 12, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Toy Camry c.c. 1998

Colour: n. Brown A/C: Insured / Std / NI / NA

Sp. Reading: 38336 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR 2BN3HK504005455

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / SIR/Im / STP / AR/Im or

Tyre Size: F: 205/65R16 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 1/9/22 D.O.I. 7/9/2022

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or & 1st

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/12/22 Lump Sum \$20,500 confirmed with Christine (red 15,113.12, 42%)

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: 18

1) \_\_\_\_\_ Date/Time, File Return to?

: Final Report

Resurvey No. of Trip: 1

Survey Fee:

2) 9/12/22-typist

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

Transportation:

: Interview (\$ \_\_\_\_\_)

\$ - RS. \$ \_\_\_\_\_

: Tech Invs (\$ \_\_\_\_\_)

Exp. Ins

: Weekend (\$ \_\_\_\_\_)

Others

Report Format : Merimen

Lump Sum / H.B.t: (\$ 20,500)

TOTAL



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722  
 Tel: 6250 0088 Fax: 6250 5545  
 Email: operation@tlauto.com.sg  
 GST No: 201700521W UEN No: 201700521W

M/S : RMG RENT-A-CAR PTE LTD  
 10 JALAN KILANG #01-01/02  
 BUKIT MERAH ENTERPRISE CENTRE,  
 SINGAPORE 159410  
 TEL : 6235 1311 FAX : 6235 5256  
 ATTN :

## ESTIMATE

PAGE: 1

NO : QUOT202209-000006(00)  
 DATE : 05/09/2022  
 POLICY NO : SD22V05556/VPZ/R09  
 VEH REG NO : SJN8488G  
 MAKE/MODEL : TOYOTA CAMRY 4-DOOR  
 SEDAN (AUTO) 2.0  
 CHASSIS NO : MR2BN3HK504005455  
 ENGINE NO : 6ARP543598  
 REG. DATE : 2019

YOUR REF NO : SLQ2309R  
 CLAIM TYPE : THIRD PARTY  
 TP INS. CO. :  
 ACCIDENT DATE : 01/09/2022  
 TP VEH REG NO : SLQ2309R

*NOT authorized  
 1/1/2022 @  
 Presumably After claim  
 16 days*

### Estimate Repair Cost to Vehicle No : SJN8488G

Description	Quantity	Unit Price	Amount
		S\$	S\$
<b>LIST PRICE</b>			
1 Bonnet	1	1,631.90	R 1,631.90 X
2 Bonnet lock	1	135.95	R 135.95 X
3 Support panel	1	1,421.90	1,421.90 7
4 Support panel top garnish	1	294.90	su 294.90 X
5 Support panel top garnish clips	8	5.50	an 44.00 X
6 Headlamp assy - RH / LH	2	4,371.80	8,743.60 7
7 Headlamp bracket -- RH / LH	2	35.60	71.20 7
8 Front grille	1	396.90	CM 396.90 ✓
9 Front grille top rubber	1	89.60	89.60 7
10 Front grille emblem	1	91.80	na 91.80 ✓
11 Front grille clips	6	5.50	na 33.00 ✓
12 Front bumper	1	556.90	su 556.90 ✓
13 Front bumper side retainer -- RH / LH	2	145.60	ols DIT 291.20 ✓
14 Front bumper reinforcement	1	366.90	366.90 7
15 Front bumper spoiler	1	225.25	225.25 7
16 Front bumper grille	1	555.90	CM 555.90 ✓
17 Front bumper grille clips	15	5.50	na 82.50 ✓
18 Front bumper fog lamp -- RH / LH	2	339.90	su 679.80 X
19 Front bumper fog lamp cover -- RH / LH	2	85.65	su 171.30 X
20 Front bumper sensor	2	496.90	993.80 7
21 Front engine undercover	1	185.90	185.90 7
22 Bootlid	1	1,145.20	su 1,145.20 ✓
23 Bootlid lock	1	399.80	na 399.80 ✓
24 Bootlid hinges -- RH / LH	2	189.55	na 379.10 X
25 Bootlid weatherstrip	1	217.95	DIT/na 217.95 ✓
26 Bootlid tools box	1	189.90	su 189.90 X
27 Bootlid spare tyre well	1	937.60	su 937.60 ✓
28 Bootlid spare tyre well top board	1	419.60	Reform 419.60 ✓
29 Bootlid logo	1	55.60	na 55.60 ✓
30 Bootlid 'CAMRY' emblem	1	69.60	na 69.60 ✓
31 Bootlid reflector -- RH / LH	2	587.60	Cut/na 1,175.20 ✓
32 Bootlid '2.0' emblem	1	39.90	na 39.90 ✓

ESTIMATE

Not



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : RMG RENT-A-CAR PTE LTD  
10 JALAN KILANG #01-01/02  
BUKIT MERAH ENTERPRISE CENTRE,  
SINGAPORE 159410

TEL : 6235 1311 FAX : 6235 5256

ATTN :

YOUR REF NO : SLQ2309R  
CLAIM TYPE : THIRD PARTY  
TP INS. CO. :  
ACCIDENT DATE : 01/09/2022  
TP VEH REG NO : SLQ2309R

## ESTIMATE

NO : QUOT202209-000006(00)  
DATE : 05/09/2022  
POLICY NO : SD22V05556/VPZ/R09  
VEH REG NO : **SJN8488G**  
MAKE/MODEL : TOYOTA CAMRY 4-DOOR  
SEDAN (AUTO) 2.0  
CHASSIS NO : MR2BN3HK504005455  
ENGINE NO : 6ARP543598  
REG. DATE : 2019

### Estimate Repair Cost to Vehicle No : SJN8488G

Description	Quantity	Unit Price	Amount
		S\$	S\$
33 Bootlid camera	1	680.20	680.20 ?
34 Bootlid Insulator	1	633.95	Sm 633.95 X
35 Bootlid insulator clips	15	12.90	nn 193.50 X
36 Rear number plate lamp -- RH / LH	2	115.85	Sm 231.70 X
37 Rear end panel	1	651.90	Rt 651.90 ✓
38 Rear end panel top garnish	1	299.60	Diy 299.60 ✓
39 Rear end panel top garnish clips	8	5.50	na 44.00 ✓
40 Taillamp assy - RH / LH	2	758.90	DIY CM 1,517.80 ✓
41 Taillamp lower bracket -- RH / LH	2	129.60	259.20 ?
42 Rear fender - LH	1	1,078.85	R 1,078.85 X
43 Rear fender inner shield -- LH	1	291.60	Sm 291.60 X
44 Rear fender inner shield clips -- LH	20	12.90	nn 258.00 X
45 Rear fender inner trim -- RH / LH	2	396.50	Sm 793.00 X
46 Rear bumper	1	619.60	Rt 619.60 ✓
47 Rear bumper retainer -- RH / LH	2	121.60	CM 243.20 ✓
48 Rear bumper reinforcement	1	319.60	Rt 319.60 ✓
49 Rear bumper reverse sensor	4	469.00	Tn 1,876.00 ✓
50 Rear bumper spoiler	1	398.90	diy 398.90 ✓
51 Rear bumper reflector -- RH / LH	2	91.80	Rt 183.60 ✓
52 Rear bumper towing cover	1	38.90	diy 38.90 ✓
53 Rear bumper air-duct -- RH / LH	2	69.60	139.20 ?
54 Rear exhaust silencer	1	886.90	886.90 ?
			33,732.85
		Less 25%	8,415.72
			25,317.13
<b>SPECIAL NET</b>			
55 Front number plate with casing	1	40.00	Rt 40.00 ✓
56 Rear number plate with casing	1	40.00	Sm 40.00 X
			80.00
<b>LABOUR</b>			
57 To remove and refit front and rear bumper sensor	1	200.00	200.00 120
58 To check and rectify wiring system (Front and Rear)	1	160.00	160.00 800
59 To remove and refit rear exhaust silencer	1	180.00	180.00 600



**TONG LUCK AUTO PTE LTD**  
 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722  
 Tel: 6250 0088 Fax: 6250 5545  
 Email: operation@tlauto.com.sg  
 GST No: 201700521W UEN No: 201700521W

M/S : **RMG RENT-A-CAR PTE LTD**  
 10 JALAN KILANG #01-01/02  
 BUKIT MERAH ENTERPRISE CENTRE,  
 SINGAPORE 159410  
 TEL : 6235 1311 FAX : 6235 5256  
 ATTN :

**ESTIMATE**

PAGE: 3

NO : QUOT202209-000006(00)  
 DATE : 05/09/2022  
 POLICY NO : SD22V05556/VPZ/R09  
 VEH REG NO : S JN8488G  
 MAKE/MODEL : TOYOTA CAMRY 4-DOOR  
 SEDAN (AUTO) 2.0  
 CHASSIS NO : MR2BN3HK504005455  
 ENGINE NO : 6ARP543598  
 REG. DATE : 2019

YOUR REF NO : SLQ2309R  
 CLAIM TYPE : THIRD PARTY  
 TP INS. CO. :  
 ACCIDENT DATE : 01/09/2022  
 TP VEH REG NO : SLQ2309R

**Estimate Repair Cost to Vehicle No : S JN8488G**

Description	Quantity	Unit Price	Amount
60 To panel beat and straighten front & rear chassis frame, rear floorboard panel, to cut and weld rear end panel, LH rear fender, rear spare tyre well, including replacement of parts and align where necessary, to refit and adjust the same.	1	S\$ 2,000.00	S\$ 2,000.00 <i>1800</i>
61 To putty and spray paint on front affected areas	1	2,500.00	2,500.00 <i>1600</i>
62 To apply rust proofing on front replaced and repaired panels	1	220.00	220.00 <i>90</i>
63 To remove and refit rear camera	1	180.00	180.00 <i>50</i>
			5,440.00
		TOTAL	S\$ 30,837.13
		ADD GST @ 7%	2,158.60
		GRAND TOTAL	S\$ 32,995.73

SINGAPORE DOLLAR THIRTY-TWO THOUSAND NINE HUNDRED NINETY-FIVE AND CENTS SEVENTY-THREE ONLY

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	01/09/2022 11:55 (SGT)
Reported by	Driver
Date of Accident	01/09/2022 07:55 (SGT)
Exact Location of Accident	AYE, Singapore
Additional Location Information	AYE TOWARDS TUAS ABOVE JURONG TOWN HALL VIADUCT
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SJN8488G

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	RMG RENT-A-CAR PTE LTD
Company Reg No	199100384R
Email Address	Elise@rmgrentacar.com.sg
Mobile Phone No	(Phone) +65-96665377
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Camry
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2000

#### INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance Pte Ltd
Policy Number / Cover Note Number	SD22V05556/VPZ/R09

#### DRIVER

Name of Driver	YO (YU) HA (BO)
Passport No/FIN	G5059988X
Date Of Birth	22/12/1972
Occupation	Indoor

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report **correctly** the details of the accident to speed up the claims process.
- 2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
- 3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **reputate policy liability**.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any **false reporting may be referred to the Police for investigation**.
- 6. The report will be forwarded by the members of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available as aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:

(i) processing, handling and/or dealing with my claim, including the settlement of the claim and any necessary investigations relating to the claim;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims, including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me, to bring about delivery of the same as well as on the external cover of envelopes/post/packages, and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively, the "Purposes")

(b) All insurer(s) who have insured vehicle(s) involved in the accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may then be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


*[Signature]*  
Policyholder's Signature / Date & Time



*[Signature]*  
Driver's Signature (if driver is not the policyholder) / Date & Time

*[Signature]*  
Witnessed by Reporting Centre Personnel

Sketch Plan



→ Teban Flyover  
AYE towards  
tugas.

C : 5L47437A

B : 53N8488G

A : 5L02309R