

ASS. REC. BY:

REF:

MSG/ 220087501kv

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1-13.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STN 8488G

Yr Regn:

12, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Camry

c.c

1998

Colour

n. Brown

A/C: Insured / Std / NI / NA

Sp. Reading

38336

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR 2BN3HK504005455

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size:

F:

205/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

1/9/22

D.O.I.

7/9/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

2/14

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : RMG RENT-A-CAR PTE LTD
10 JALAN KILANG #01-01/02
BUKIT MERAH ENTERPRISE CENTRE,
SINGAPORE 159410

TEL : 6235 1311

FAX : 6235 5256

ATTN :

YOUR REF NO : SLQ2309R
CLAIM TYPE : THIRD PARTY
TP INS. CO. :

ACCIDENT DATE : 01/09/2022

TP VEH REG NO : SLQ2309R

ESTIMATE

NO : QUOT202209-000006(00)
DATE : 05/09/2022
POLICY NO : SD22V05556/VPZ/R09
VEH REG NO : SJN8488G
MAKE/MODEL : TOYOTA CAMRY 4-DOOR
SEDAN (AUTO) 2.0
CHASSIS NO : MR2BN3HK504005455
ENGINE NO : 6ARP543598
REG. DATE : 2019

*Not authorized
L/Rep @
Permy After claim
16 days*

Estimate Repair Cost to Vehicle No : SJN8488G

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Bonnet	1	1,631.90	<i>R</i> 1,631.90 <i>X</i>
2 Bonnet lock	1	135.95	<i>R</i> 135.95 <i>X</i>
3 Support panel	1	1,421.90	1,421.90 <i>7</i>
4 Support panel top garnish	1	294.90	<i>su</i> 294.90 <i>X</i>
5 Support panel top garnish clips	8	5.50	<i>su</i> 44.00 <i>X</i>
6 Headlamp assy - RH / LH	2	4,371.80	8,743.60 <i>7</i>
7 Headlamp bracket -- RH / LH	2	35.60	71.20 <i>7</i>
8 Front grille	1	396.90	<i>CM</i> 396.90 <i>✓</i>
9 Front grille top rubber	1	89.60	89.60 <i>7</i>
10 Front grille emblem	1	91.80	<i>su</i> 91.80 <i>✓</i>
11 Front grille clips	6	5.50	<i>su</i> 33.00 <i>✓</i>
12 Front bumper	1	556.90	<i>su</i> 556.90 <i>✓</i>
13 Front bumper side retainer -- RH / LH	2	145.60	<i>ols D, 7</i> 291.20 <i>✓</i>
14 Front bumper reinforcement	1	366.90	366.90 <i>7</i>
15 Front bumper spoiler	1	225.25	225.25 <i>7</i>
16 Front bumper grille	1	555.90	<i>CM</i> 555.90 <i>✓</i>
17 Front bumper grille clips	15	5.50	<i>McC</i> 82.50 <i>✓</i>
18 Front bumper fog lamp -- RH / LH	2	339.90	<i>su</i> 679.80 <i>X</i>
19 Front bumper fog lamp cover -- RH / LH	2	85.65	<i>su</i> 171.30 <i>X</i>
20 Front bumper sensor	2	496.90	993.80 <i>7</i>
21 Front engine undercover	1	185.90	185.90 <i>7</i>
22 Bootlid	1	1,145.20	<i>R</i> 1,145.20 <i>✓</i>
23 Bootlid lock	1	399.80	<i>McC</i> 399.80 <i>✓</i>
24 Bootlid hinges -- RH / LH	2	189.55	<i>R</i> 379.10 <i>X</i>
25 Bootlid weatherstrip	1	217.95	<i>Dis/Re</i> 217.95 <i>✓</i>
26 Bootlid tools box	1	189.90	<i>su</i> 189.90 <i>X</i>
27 Bootlid spare tyre well	1	937.60	<i>R</i> 937.60 <i>✓</i>
28 Bootlid spare tyre well top board	1	<i>Reform</i> 419.60	419.60 <i>✓</i>
29 Bootlid logo	1	55.60	<i>su</i> 55.60 <i>✓</i>
30 Bootlid 'CAMRY' emblem	1	69.60	<i>su</i> 69.60 <i>✓</i>
31 Bootlid reflector -- RH / LH	2	<i>Cut/CM</i> 587.60	1,175.20 <i>✓</i>
32 Bootlid '2.0' emblem	1	39.90	<i>su</i> 39.90 <i>✓</i>



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : RMG RENT-A-CAR PTE LTD
10 JALAN KILANG #01-01/02
BUKIT MERAH ENTERPRISE CENTRE,
SINGAPORE 159410

TEL : 6235 1311 FAX : 6235 5256

ATTN :

YOUR REF NO : SLQ2309R
CLAIM TYPE : THIRD PARTY
TP INS. CO. :
ACCIDENT DATE : 01/09/2022
TP VEH REG NO : SLQ2309R

ESTIMATE

NO : QUOT202209-000006(00)
DATE : 05/09/2022
POLICY NO : SD22V05556/VPZ/R09
VEH REG NO : SJN8488G
MAKE/MODEL : TOYOTA CAMRY 4-DOOR
SEDAN (AUTO) 2.0
CHASSIS NO : MR2BN3HK504005455
ENGINE NO : 6ARP543598
REG. DATE : 2019

Estimate Repair Cost to Vehicle No : SJN8488G

Description	Quantity	Unit Price	Amount
		S\$	S\$
33 Bootlid camera	1	680.20	680.20 ?
34 Bootlid Insulator	1	633.95	Sm 633.95 X
35 Bootlid insulator clips	15	12.90	nn 193.50 X
36 Rear number plate lamp -- RH / LH	2	115.85	Sm 231.70 X
37 Rear end panel	1	651.90	Rt 651.90 ✓
38 Rear end panel top garnish	1	299.60	Dir 299.60 ✓
39 Rear end panel top garnish clips	8	5.50	na 44.00 ✓
40 Taillamp assy - RH / LH	2	758.90	1,517.80 Lt
41 Taillamp lower bracket -- RH / LH	2	129.60	259.20 ?
42 Rear fender - LH	1	1,078.85	R 1,078.85 X
43 Rear fender inner shield -- LH	1	291.60	Sm 291.60 X
44 Rear fender inner shield clips -- LH	20	12.90	nn 258.00 X
45 Rear fender inner trim -- RH / LH	2	396.50	Sm 793.00 X
46 Rear bumper	1	619.60	Rt 619.60 ✓
47 Rear bumper retainer -- RH / LH	2	121.60	cm 243.20 ✓
48 Rear bumper reinforcement	1	319.60	Rt 319.60 ✓
49 Rear bumper reverse sensor	4	469.00	Tt 1,876.00 ✓
50 Rear bumper spoiler	1	398.90	Dir 398.90 ✓
51 Rear bumper reflector -- RH / LH	2	91.80	Rt 183.60 ✓
52 Rear bumper towing cover	1	38.90	Dir 38.90 ✓
53 Rear bumper air-duct -- RH / LH	2	69.60	139.20 ?
54 Rear exhaust silencer	1	886.90	886.90 ?
			33,732.85
		Less 25%	8,415.72
			25,317.13
SPECIAL NET			
55 Front number plate with casing	1	40.00	Rt 40.00 ✓
56 Rear number plate with casing	1	40.00	Sm 40.00 X
			80.00
LABOUR			
57 To remove and refit front and rear bumper sensor	1	200.00	200.00 120
58 To check and rectify wiring system (Front and Rear)	1	160.00	160.00 800
59 To remove and refit rear exhaust silencer	1	180.00	180.00 600



TONG LUCK AUTO PTE LTD
160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722
Tel: 6250 0088 Fax: 6250 5545
Email: operation@tlauto.com.sg
GST No: 201700521W UEN No: 201700521W

M/S : RMG RENT-A-CAR PTE LTD
10 JALAN KILANG #01-01/02
BUKIT MERAH ENTERPRISE CENTRE,
SINGAPORE 159410
TEL : 6235 1311 FAX : 6235 5256
ATTN :

YOUR REF NO : SLQ2309R
CLAIM TYPE : THIRD PARTY
TP INS. CO. :
ACCIDENT DATE : 01/09/2022
TP VEH REG NO : SLQ2309R

ESTIMATE

NO : QUOT202209-000006(00)
DATE : 05/09/2022
POLICY NO : SD22V05556/VPZ/R09
VEH REG NO : SJN8488G
MAKE/MODEL : TOYOTA CAMRY 4-DOOR
SEDAN (AUTO) 2.0
CHASSIS NO : MR2BN3HK504005455
ENGINE NO : 6ARP543598
REG. DATE : 2019

PAGE: 3

Estimate Repair Cost to Vehicle No : SJN8488G

Description	Quantity	Unit Price	Amount
60 To panel beat and straighten front & rear chassis frame, rear floorboard panel, to cut and weld rear end panel, LH rear fender, rear spare tyre well, including replacement of parts and align where necessary, to refit and adjust the same.	1	S\$ 2,000.00	S\$ 2,000.00
61 To putty and spray paint on front affected areas	1	2,500.00	2,500.00
62 To apply rust proofing on front replaced and repaired panels	1	220.00	220.00
63 To remove and refit rear camera	1	180.00	180.00
			5,440.00
		TOTAL	S\$ 30,837.13
		ADD GST @ 7%	2,158.60
		GRAND TOTAL	S\$ 32,995.73

SINGAPORE DOLLAR THIRTY-TWO THOUSAND NINE HUNDRED NINETY-FIVE AND CENTS SEVENTY-THREE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	01/09/2022 11:55 (SGT)
Reported by	Driver
Date of Accident	01/09/2022 07:55 (SGT)
Exact Location of Accident	AYE, Singapore
Additional Location Information	AYE TOWARDS TUAS ABOVE JURONG TOWN HALL VIADUCT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJN8488G

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	RMG RENT-A-CAR PTE LTD
Company Reg No	199100384R
Email Address	Elise@rmgrentacar.com.sg
Mobile Phone No	(Phone) +65-96665377
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Camry
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2000

INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance Pte Ltd
Policy Number / Cover Note Number	SD22V05556/VPZ/R09

DRIVER

Name of Driver	YO (YU) HA (BO)
Passport No/FIN	G5059988X
Date Of Birth	22/12/1972
Occupation	Indoor



SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any **false reporting** may be **referred to the Police for investigation**.
6. The report will be forwarded by the members of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available as aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I/We (undersigned) acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claim, including the settlement of the claim and any necessary investigations relating to the claim;

(ii) investigating the accident and/or my claim;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claim, including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packets; and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claim.


(Collectively, the "Purposes")


(b) All insurer(s) who have insured vehicle(s) involved in the accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/then be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time




Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan



→ Teban Flyover
A/E towards
tugs.

C : 6L47437A

B : 53N8488G

A : 6L02309R