

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

05/09/2022 10:12

JOB-NO: 50114452

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
 ADDRESS: 383 SIN MING DRIVE
 SINGAPORE 575717 0

CONTACT: 65533880
 64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHC0272X TRANS: AUTO
 MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 DI
 OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD
 JOB-CODE: TP SA: Ding Auto User 2

CHASSIS: KMHC851CVLU178668
 ENGINE: G4LEKU362985

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	1.00	1,400.00	0.00	1,400.00	600 /	Y	_____
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	170.00	0.00	170.00	30 /	Y	_____
3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	1.00	220.00	0.00	220.00	30 /	Y	_____
4 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	240.00	0.00	240.00	30 /	Y	_____
5 TO REFIT REAR REVERSE SENSOR	1.00	100.00	0.00	100.00	30 /	Y	_____
6 TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	1.00	120.00	0.00	120.00	X	Y	_____
7 TO CHECK AND REPAIR WIRE HARNESS	1.00	150.00	0.00	150.00	X	Y	_____
8 TO RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	200 /	Y	_____
9 TO RESPRAY REAR BUMPER CENTER MOULDING	1.00	250.00	0.00	250.00	150 /	Y	_____
10 TO RESPRAY REAR BUMPER LOWER MOULDING	1.00	250.00	0.00	250.00	X	Y	_____
11 TO RESPRAY REAR REVERSE SENSOR	1.00	250.00	0.00	250.00	X 80 /	Y	_____
12 TO RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00	200 /	Y	_____
13 TO RESPRAY REAR TAILGATE PANEL	1.00	250.00	0.00	250.00	200 /	Y	_____
14 TO RESPRAY REAR QUARTER PANEL	1.00	250.00	0.00	250.00	200 /	Y	_____
TOTAL:		4,150.00	0.00	4,150.00	1750		_____
<u>MATERIALS</u>							
1 REAR BUMPER COVER / OR	1.00	459.40	91.88	367.52	L	Y	_____
2 REAR LH BUMPER RETAINER / OR	1.00	33.10	6.62	26.48	L	Y	_____
3 REAR RH BUMPER RETAINER X nn	1.00	33.10	6.62	26.48	L	Y	_____
4 REAR BUMPER CENTER MOULDING X nn	1.00	270.10	54.02	216.08	L	Y	_____
5 REAR LH BUMPER REFLECTOR cut? 50	1.00	58.60	11.72	46.88	L	Y	_____
6 REAR BUMPER REINFORCEMENT ? X nn	1.00	294.80	58.96	235.84	L	Y	_____
7 REAR LH BUMPER REINFORCEMENT BRACKET ? X nn	1.00	138.10	27.62	110.48	L	Y	_____
8 REAR RH BUMPER REINFORCEMENT BRACKET ? X nn	1.00	138.10	27.62	110.48	L	Y	_____
9 REAR BUMPER LOWER MOULDING X nn	1.00	47.50	9.50	38.00	L	Y	_____
10 REAR FOG LAMP X nn	1.00	201.50	40.30	161.20	L	Y	_____
11 REAR LICENCE PLATE LAMP ASSY X nn	1.00	96.64	19.33	77.31	L	Y	_____
12 REAR BUMPER TOWING COVER - nn	1.00	9.10	1.82	7.28	L	Y	_____
13 REAR BUMPER WIRE HARNESS X nn	1.00	210.10	42.02	168.08	L	Y	_____

G-STAR-WI-ET-001-02-Rev00

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
14 REAR BUMPER CENTER UNDER COVER X	1.00	28.70	5.74	22.96	L	Y	
15 REAR LH BUMPER UNDER COVER R - BR	1.00	27.50	5.50	22.00	L	Y	
16 SMART KEY ANTENNA - BR	1.00	40.50	8.10	32.40	L	Y	
17 REAR LH BLIND SPOT DETECTION UNIT	1.00	1,874.40	374.88	1,499.52	L	Y	
18 REAR TAILGATE HYUNDAI EMBLEM - nk	1.00	68.20	13.64	54.56	L	Y	
19 REAR TAILGATE IONIQ EMBLEM - nk	1.00	48.20	9.64	38.56	L	Y	
20 REAR TAILGATE HYBRID EMBLEM - nk	1.00	51.20	10.24	40.96	L	Y	
21 REAR BOOT WEATHERSTRIP - Tn	1.00	127.40	25.48	101.92	L	Y	
22 REAR BOOT LOCK X nn	1.00	224.00	44.80	179.20	L	Y	
23 TAILLAMP LH X nn	1.00	905.20	181.04	724.16	L	Y	
24 REAR LH QUARTER PANEL X R	1.00	1,768.30	353.66	1,414.64	L	Y	
25 REAR LH QUARTER PANEL AIR VENT X nn	1.00	57.60	11.52	46.08	L	Y	
26 REAR LH WHEEL RIM COVER X nn	1.00	346.40	69.28	277.12	L	Y	
27 REAR END PANEL X nn	1.00	532.00	106.40	425.60	L	Y	
28 REAR BUMPER CLIP SET - nk	1.00	55.00	0.00	55.00	S	Y	
29 REAR REVERSE SENSOR SET - BR	2.00	300.00	0.00	300.00	S	Y	
30 REAR BUMPER PROTECTOR - nk	1.00	120.00	0.00	120.00	S	Y	
31 REAR TAILGATE "COMFORT DELGRO" - nk	1.00	100.00	0.00	100.00	S	Y	
STICKER							
32 REAR TAILGATE "6552-1111" STICKER - nk	1.00	100.00	0.00	100.00	S	Y	
33 REAR TAILGATE "BOOK NOW" STICKER - nk	1.00	100.00	0.00	100.00	S	Y	
34 REAR LICENCE PLATE NUMBER WITH FRAME - nk	1.00	80.00	0.00	80.00	S	Y	
35 REAR BUMPER UNDER COVER CLIP SET X nn	1.00	55.00	0.00	55.00	S	Y	
36 TAILLAMP GUIDE CLIP SET X nn	1.00	50.00	0.00	50.00	S	Y	
37 FUEL FLAP "PETROL ONLY" STICKER X nk	1.00	100.00	0.00	100.00	S	Y	
TOTAL:		9,149.74	1,617.95	7,531.79			

TOTAL PARTS & LABOUR : 13,299.74 1,617.95 11,681.79

EXCESS/LOADING:\$ 0.00

No. Of Day: _____

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: \$\$

DATE OF SURVEY: _____

SURVEYED BY: _____

CONTACT NO: _____

FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR
STA AUTOCENTRE
TEL: _____

FAX: _____

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

G-STAR-WI-ET-001-02-Rev00