



LION CITY RENTALS PTE LTD
4 Jalan Besut S(619557)

Ms NTUC INCOME INSURANCE CO-OPERATIVE LTD

Date : 19 Aug 2022

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. : SLG7442H
CHASSIS NO : JM6BM42A8G0343563
MAKE / MODEL : Mazda 3
DATE OF ACCIDENT: 19 Aug 2022
YOUR INSURED VEHICLE NUMBER : SLG349R

	<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	REAR BUMPER ✓ BR	1.00	\$998.00	\$998.00
2	REAR BUMPER SIDE RETAINER LH / RH ✓ BR	2.00	\$65.50	\$131.00
3	REAR BUMPER REFLECTOR LH / RH ✓ CUT 2.00 1	1.00	\$75.10	\$150.20
4	REAR BUMPER REINFORCEMENT ✓ BT	1.00	\$582.40	\$582.40
5	REAR BUMPER LOWER COVER × NN	1.00	\$389.20	\$389.20
6	TAIL LAMP LOWER BRACKET RH × NN	1.00	\$55.00	\$55.00
7	REAR END PANEL ?	1.00	\$548.60	\$548.60
8	REAR END PANEL TOP GARNISH × NN	1.00	\$298.20	\$298.20
LIST TOTAL S\$:				\$3,152.60
25.00% DISCOUNT S\$:				\$788.15
				\$2,364.45

SPECIAL NETT

1	Reverse sensor	1 SET	Shorted	\$280.00	200 ✓
2	Bumper clips	1 SET	NEC	\$50.00	30 ✓
Special Nett Total S\$:				\$330.00	

LABOUR CHARGES

1	To labour charge for removing out front rh fender & front rh door to facilitate repairs and replacment of damaged parts	\$1,000.00	250
2	To respray front rh fender & front rh door	\$800.00	400

LABOUR TOTAL S\$:	\$1,800.00
TOTAL S\$:	\$4,494.45
7% GST	\$318.61
GRAND TOTAL S\$:	\$4,809.06

Steve (LKK)
07/09/2022
Without Prejudice
4 days
L/S
Resurvey After Spray

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: