

LION CITY RENTALS PTE LTD 4 Jalan Besut S(619557)

Ms NTUC INCOME INSURANCE CO-OPERATIVE LTD

19 Aug 2022 Date:

MOTOR CLAIMS DEPT Attn:

ESTIMATE

SLG7442H **VEHICLE NO.:**

CHASSIS NO: JM6BM42A8G0343563

MAKE / MODEL : Mazda 3 DATE OF ACCIDENT: 19 Aug 2022

YOUR INSURED VEHICLE NUMBER: SLG349R

	PARTS DISCRIPTION	<u>QTY</u>	UNIT PRICE	LIST PRICE
1	REAR BUMPER ✓ BR	1.00	\$998.00	\$998.00
2	REAR BUMPER SIDE RETAINER LH / RH BR	2.00	\$65.50	\$131.00
3	REAR BUMPER REFLECTOR LH / RH ✓ CUT	2.0 0 1	\$75.10	\$150.20
4	REAR BUMPER REINFORCEMENT ✓ BT	1.00	\$582.40	\$582.40
5	REAR BUMPER LOWER COVER X	1.00	\$389.20	\$389.20
6	TAIL LAMP LOWER BRACKET RH X	1.00	\$55.00	\$55.00
7	REAR END PANEL ?	1.00	\$548.60	\$548.60
8	REAR END PANEL TOP GARNISH X	1.00	\$298.20	\$298.20
			LIST TOTAL S\$:	\$3,152.60
		25.00% DISCOUNT S\$:		\$788.15
				\$2,364.45

SPECIAL NETT

1	Reverse sensor	1 SET	Shorted	\$280.00 200 🗸
2	Bumper clips	1 SET	NEC	\$50.00 30 🗸
		Special Nett Total S\$:		\$330.00

LABOUR CHARGES

To labour charge for removing out front rh fender & front rh door to faciliate 1 \$1,000.00 250 repairs and replacment of damaged parts

2 To respray front rh fender & front rh door \$800.00 400

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Steve (LKK) 07/09/2022 Without Prejudice 4 days L/S

Resurvey After Spray

LABOUR TOTAL SS: \$1,800.00 TOTAL S\$: \$4,494.45 7% GST \$314.61 GRAND TOTAL S\$: \$4,809.06