

Mitsubishi HC Capital Asia Pacific Pte. Ltd.
Automotive Workshop

No. 8 Fourth Lok Yang Road Singapore 629705

Tel : 64663022 Fax : 68966591

Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE Dated 30/08/2022

NTUC INCOME

ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 24/08/2022 : 18:55hr

VRN : GBG1104S

MODEL : NISSAN NV200

PARTS REPLACEMENT

	Qty	S\$ Unit	S\$ Amt
1 RH Rocker panel X AN	1	\$ 2,400.00	\$ 2,400.00
2 Rear RH sliding door X R	1	\$ 2,160.00	\$ 2,160.00
3 rear RH fender X R	1	\$ 2,400.00	\$ 2,400.00
4 rear Bumper	1	\$ 720.00	\$ 720.00
5 rear RH bumper side retainer ? X AN	1	\$ 72.00	\$ 72.00
6 rear RH wheel rim cover	1	\$ 240.00	\$ 240.00
7 RH taillamp X AN	1	\$ 288.00	\$ 288.00

All List -30%

Special Nett

8 rear bumper clips (set) / PR	1	\$ 60.00	\$ 30.00
9 front RH tyre X AN	1	\$ 350.00	\$ 350.00

PARTS TOTAL

\$ 8,280.00

\$ 2,484.00

\$ 5,796.00

\$ 410.00

\$ 6,206.00

B. Labour Charges

- 1 Panel beat, cut, weld, re-align & replace damaged parts of affected areas.
- 2 Putty, Blend And Spray Paint on Affected Area
- 3 Check wiring, re-align taillamp and ensure proper functioning.
- 4 Check, re-adjust and computerise wheel alignment/side slip test.
- 5 Remove, replace and balance rim / tyre. (per rim)
- 6 Check, re-adjust and computerise wheel alignment/side slip test.
- 7 Remove and reinstall 2/4 piece of bumper sensors.
- 8 Remove, replace and balance rim / tyre. (per rim)

LABOURS TOTAL

\$ 850.00
\$ 720.00
\$ 80.00
\$ 180.00
\$ 40.00
\$ 180.00
\$ 120.00
\$ 40.00

\$ 2,210.00

Grand Total

Add 7% GST

Nett Total

\$ 8,416.00

\$ 589.12

\$ 9,005.12

No. of repair days: 15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

CUSTOMER SIGNATURE

Acknowledged by Repairer

Signature:

Date:

MITSUBISHI HC CAPITAL ASIA PACIFIC PTE LTD



L/S-13/3.60

=1300