



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INCOME INSURANCE LTD	Ref: CS/INC22008761/Dqy3m4
75 BRAS BASAH ROAD	Date: 27/10/2022
INCOME CENTRESINGAPORE 189557	
ATTN: CHRYLLIS QUAH	Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMH 7894U	Veh. Inspected	GBF 4585Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1187324-001	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	06/09/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTFAT35Y80K206996	Colour	SILVER
Odometer	119048 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	MICHELIN	5 mm
L/H Front Tyre	195 R15C	MICHELIN	5 mm
R/H Rear Tyre	155 R12 (D/D)	YOKOHAMA	5/5 mm
L/H Rear Tyre	155 R12 (D/D)	YOKOHAMA	5/5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/08/2022	Inspection Date	06/09/2022
Survey held at	GOH LEE HWA AUTOMOBILE PTE LTD BLK.5033 #01-255 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569536		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**