



AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)

Tel : 6702 1555

Co. Reg No. : 201500047H GST No. : 201500047H

Email : admin@autobacs.com.sg

TO	: NTUC (SLX6405H)	DATE	: 05-09-2022
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
VEHICLE DETAILS		LKK Auto Consultants hence notify the Repairer of the following: <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged parts for resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 	
VEHICLE NO.	: SJP1509R		
MODEL / MAKE	: TOYOTA ALLION		
CHASSIS NO.	: NZT260-3040673		
ACCIDENT DETAIL			
DATE	: 26-08-2022		
TIME	: 2135HRS		

Acknowledged by Repairer
 Signature: *[Signature]*
 Date: *07/09/22*

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST	TOTAL LIST
1	FRONT DOOR SIDE MIRROR RH	1	\$ 1,235.00	\$ 1,235.00
2	FRONT DOOR SIDE MIRROR COVER RH	1	\$ 105.00	\$ 105.00
TOTAL				\$ 1,340.00
LESS -25%				\$ 335.00
SUB TOTAL				\$ 1,005.00

750
~~*645*~~
70
T 820
~~*-19,205*~~
F(615)

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 200.00	<i>/ 80</i>	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 200.00	<i>/ 80</i>	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 80.00	<i>α</i>	
TOTAL	\$ 480.00		<i>Total 160</i>

ESTIMATE REPORT

TOTAL PARTS COST :	\$ 1,005.00	<i>\$ 615</i>
TOTAL LABOUR COST :	\$ 480.00	<i>\$ 160</i>
TOTAL REPAIR COST :	\$ 1,485.00	

Mohamed Irfan
90097659

1 day L/S

After Repair survey

~~*1485*~~ *cost = \$775*
-20% = 155
Total cost = \$600