



ESTABLISHED 1984

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22008762/Svy3m4

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 22/09/2022

ATTN: DAVID PHUA

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLX 6405H	Veh. Inspected	SJP 1509R
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1187428-001	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	06/09/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALLION 1.5 A	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	NZT2603040673	Colour	SILVER
Odometer	168737 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	TOURADOR	6 mm
L/H Front Tyre	205/55 R16	TOURADOR	6 mm
R/H Rear Tyre	205/55 R16	NEXEN	5 mm
L/H Rear Tyre	205/55 R16	NEXEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/08/2022	Inspect Date / Time	06/09/2022 (01:18 PM)
Survey held at	AUTOBACS CAR CARE (S) PTE LTD 8 KAKI BUKIT AVENUE 4 #08-40/45/46 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. RemarksA)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.**5b. Estimate Days of Repair**ESTIMATED NORMAL PERIOD FOR REPAIR: **1 Working Days**