

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0760/2022/EQ  
**DATE** : 2-Sep-22  
**WIP** : 40052

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 06/09/2022**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MR YEO KOK PENG SEBASTIAN  
**ADDRESS** : 23 UPPER SERANGOON VIEW  
#13-02  
SINGAPORE 534047  
**TELEPHONE** : HP +65 98194641  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 7210060229-01  
**VEHICLE NO** : **SNA 3160 E**  
**MODEL CODE** : AUDI Q3 SPORTBACK 1.4 TFS  
**MODEL YEAR** : 16/6/2021  
**ENGINE NO** : CZD C40418  
**CHASSIS NO** : WAUZZZF32M1119698  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 31-Aug-22  
**PLACE OF ACCIDENT** : BOATHOUSE RESIDENCE BASEMENT CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 3160 E**

| S/N                         | NATURE OF JOBS                                                                                                                           |        | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|-------------------------------|
| 1                           | TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.                                  | S/N \$ | 400.00               | ✓ ✓                           |
| 2                           | TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR. | S/N \$ | 280.00               | X Xnn                         |
| 3                           | TO DISMANTLE AND RENEW LHS REAR DOOR. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.   | \$     | 1,600.00             | 500 ✓                         |
| 4                           | TO RESPRAY LHS REAR DOOR, LHS FRONT DOOR, LHS REAR FENDER, 2 DOOR COVERS AND LHS REAR WHEEL ARCH TRIM.                                   | \$     | 4,000.00             | 1500. ✓                       |
| 5                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                           | S/N \$ | 192.00               | ✓ ✓                           |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                          | : \$   | <b>6,472.00</b>      |                               |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 3160 E**

|                             |                                          |     | DAMAGED PARTS & PRICES |              |
|-----------------------------|------------------------------------------|-----|------------------------|--------------|
| S/N                         | PARTS DESCRIPTION                        | QTY | S/NETT                 | REMARKS      |
| 1                           | REAR DOOR - LH                           | 1   | \$ 3,028.00            | bt ✓ 2422.40 |
| 2                           | REAR OUTER DOOR SEAL - LH                | 1   | \$ 151.00              | ner ✓ 120.40 |
| 3                           | REAR DOOR CATCH - LH                     | 1   | \$ 134.00              | X 106.80 btv |
| 4                           | REAR INNER DOOR SEAL - LH                | 1   | \$ 213.00              | X nn         |
| 5                           | REAR DOOR SILL PANEL - LH                | 1   | \$ 151.00              | X nn         |
| 6                           | REAR WINDOW WITHOUT REGULATOR MOTOR - LH | 1   | \$ 302.00              | ? X nn       |
| 7                           | REAR WINDOW REGULATOR MOTOR - LH         | 1   | \$ 300.00              | ? X nn       |
| 8                           | REAR DOOR CONTROL UNIT - LH              | 1   | \$ 464.00              | ? X nn       |
| 9                           | REAR DOOR COVER - LH                     | 1   | \$ 368.00              | dis ✓ 294    |
| 10                          | REAR DOOR PANEL - LH                     | 1   | \$ 2,659.00            | X nn         |
| 11                          | REAR WHEEL COVER - LH                    | 1   | \$ 566.00              | mis ✓ 452.40 |
| 12                          | REAR WHEEL HOUSING LINER - LH            | 1   | \$ 262.00              | ? X nn       |
| 13                          | REAR WHEEL SPOILER - LH                  | 1   | \$ 44.00               | ? X nn       |
| 14                          | FRONT DOOR COVER - LH                    | 1   | \$ 390.00              | X nn         |
| 15                          | SUNDRIES                                 |     | \$ 400.00              | ? 9.28 nec ✓ |
| <b>TOTAL SPARE PARTS</b>    |                                          | :   | <b>\$ 9,432.00</b>     |              |
| <b>TOTAL LABOUR CHARGES</b> |                                          | :   | <b>\$ 6,472.00</b>     |              |
| <b>GRAND TOTAL</b>          |                                          | :   | <b>\$ 15,904.00</b>    |              |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6641 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :  
SURVEYED DATE :  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS :

Tanpin 97495747  
Not authorised, Revert.  
04 days Ex: to be advise  
Plp Resurvey before paint  
tanpin@thant.com

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT