

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22008769/EQY3Q2**Date:** 28/09/2022REFERENCE

Insured/Claimant: GOH KOK CHUAN Policy No: DMPCSNW00103522200

Date of Loss: 02/09/2022

Nature of Claim: OD

Claim No: SNM22D206276/C01/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMZ9596Y**

Make &amp; Model: AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)

Engine No: CVK081671

Reg. Date: 31/05/2019 (Man. Year: 2019)

Chassis No: WAUZZZF4XKA071227

Colour: White

Odometer: 80969 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$139,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17

Rear Tyre Size: 215/50 R17

Front Left Side: Michelin 4 mm

Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm

Rear Right Side: Michelin 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,180.00	2,180.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	550.00	250.00	31.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,980.00</b>	<b>2,730.00</b>	<b>250.00</b>	<b>8.39</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,200.00</b>		
<b>(S\$)</b>	2,980.00	2,200.00	780.00	26.17
<b>+ GST 7.00/7.00% (S\$)</b>	208.60	154.00	54.60	26.17
<b>Nett Amount (S\$)</b>	<b>3,188.60</b>	<b>2,354.00</b>	<b>834.60</b>	<b>26.17</b>

INSPECTION

Date of Assignment: 06/09/2022

Date Inspected: 13/09/2022 Inspected At:

Goldbell Engineering Pte Ltd (Pandan)  
Blk K, Pandan Loop Industrial Estate, #01-12  
Singapore 128219

Estimated Period of Repair: 4.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2022)
<b>Parts:</b> 143	AUDI A4 2.0 SEDAN TFSI S-TRONIC (NAV) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SMZ9596Y)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Broken	1,100.00 F	*1,100.00 F	
2	1		*FRONT BUMPER GRILL	Broken	580.00 F	*580.00 F	
3	1		*FRONT REINFORCEMENT	Bent	465.00 F	*465.00 F	
4	1		*FRONT NO PLATE WITH HOLDER	Cut	35.00 F	*35.00 F	
					<b>Total Parts (\$)</b>	<b>2,180.00</b>	<b>2,180.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RESPRAY FRONT BUMPER	New	350.00	250.00
2	REMOVE INSTALL FRONT BUMPER ,FRONT GRILL AND REINFORCEMENT	New	450.00	300.00
			<b>Gross Labour Cost (\$)</b>	<b>800.00</b>
				<b>550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >