

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 () TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: 0/-
 (Client's Record)
 Make of Veh: _____

Veh No: SM29596Y Yr Regn: 31/5/19
 Type: () Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Traller or _____
 Make: Audi A4 c.c. 1984
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 80970 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAU2ZZP0XKACT1997
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 215/50R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / () MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. 4 mm L/Bal. 4 mm
 D.O.A. 2/9/22 D.O.I. 13/9/22
 Survey held at Gokhbell
 Des. of Damages: () Front / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
<u>21/09/22 @ 3.41pm</u>	<u>finalised with Ramesh LS \$2200, 4 days by email. (Red \$780, 26%)</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) 21/09 Typist
 Date/Time, File Return to?

Days Of Repair: 4
 Resurvey No. of Trip: 1

Survey Fee:	
Transportation:	
\$ + RS. SI	
Photos	
Others	
TOTAL	

2) _____
 Report Format: MER-OD
 Lump Sum 2200

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	DMPCSNW00103522200	Date of Loss:	02/09/2022
Vehicle Reg. No.:	SMZ9596Y	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GOH KOK CHUAN		
Driver:	GOH KOK CHUAN		
Make/Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Vehicle Reg. Date:	21/03/2019
Vehicle Colour:	White		
Engine No:	GIKCQW1LW	Chassis No:	189EJK8CLWAAL
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	GOLDBELL ENGINEERING PTE LTD (TUAS)		

COST OF CLAIMS	Amount
Parts	2,180.00
Miscellaneous Items	0.00
Labour	800.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,980.00
+ GST 7.00% (S\$)	208.60
Nett Amount (S\$)	3,188.60

This claim is handled by: RAMESH S/O SOMASUNDREM

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Sep 2022)
 Parts: 143 AUDI A4 2.0 SEDAN TFSI S-TRONIC (NAV) (A) (Catalogue.Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Goldbell Engineering Pte Ltd/SMZ9596Y/12/09/2022 10:20
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER / BR	0.00	0.00	*1,100.00 F
2	1		*FRONT BUMPER GRILL / BR	0.00	0.00	*580.00 F
3	1		*FRONT REINFORCEMENT / ST	0.00	0.00	*465.00 F
4	1		*FRONT NO. PLATE WITH HOLDER / CVT	0.00	0.00	*35.00 F
Total Parts (S\$) (COS pie)						2,180.00

F=Franchise part.

Goldbell Engineering Pte Ltd/SMZ9596Y/12/09/2022 10:20. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	RESPRAY FRONT BUMPER	New	250 350.00
2	REMOVE INSTALL FRONT BUMPER, FRONT GRILL AND REINFORCEMENT.	New	200 450.00
Gross Labour Cost (S\$)			800.00

Goldbell Engineering Pte Ltd/SMZ9596Y/12/09/2022 10:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FUSO AIRMAN.

bizSAFE
S T & R



Steve CLKK

8322 8813

OO-MAL

EXCESS - ?

4 dys

~~PAR~~ LIS

by BLG

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: