

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Cecilia Lee

Date: 15 Sep 2022

Preliminary Advice

Vehicle No	: SMZ9596Y	Accident Date	: 02/09/2022
Make	: AUDI A4	Policy No.	: DMPCSNW00103522200
Assignment Date	: 06/09/2022	Excess	: S\$0.00
Date of Inspection	: 06/09/2022	Est. Duration of Repair	: 3
Inspection At	: GOLDBELL ENGINEERING PTE LTD (PANDAN) BLK K, PANDAN LOOP INDUSTRIAL ESTATE, #01-12 SINGAPORE 128219		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,980.00
Revised Amount	:S\$	2,730.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,730.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 139,000.00
COE / PARF Rebate	:S\$ 57,972.00

Salvage Value	:S\$
Margin for Repair	:S\$ 81,028.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.