



Industrial Vehicles. Financial Services.  
41,000 Served. And Counting.

**GOLDBELL ENGINEERING PTE LTD**  
Main Office: 8 Tuas Avenue 14 Singapore 630892 Tel: 6831 9007 Fax: 6551 3075  
Finance: 8 Tuas Avenue 18 Singapore 630892 Tel: 6831 9007 Fax: 6982 4508  
Website: www.goldbell.com.sg  
Co. Reg. No: 19800363G

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM			
Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	DMPCSNW00103522200	Date of Loss:	02/09/2022
Vehicle Reg. No.:	SMZ9596Y	Driveable?:	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GOH KOK CHUAN		
Driver:	GOH KOK CHUAN		
Make/Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Vehicle Reg. Date:	21/03/2019
Vehicle Colour:	White		
Engine No:	G1KCQW1LW	Chassis No:	I89EJK8CLWAAL
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	GOLDBELL ENGINEERING PTE LTD (TUAS)		

COST OF CLAIMS	Amount
Parts	2,180.00
Miscellaneous Items	0.00
Labour	800.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$\$)</b>	<b>2,980.00</b>
<b>+ GST 7.00% (\$\$)</b>	<b>208.60</b>
<b>Nett Amount (\$\$)</b>	<b>3,188.60</b>

This claim is handled by: **RAMESH S/O SOMASUNDREM**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

- S-line front bumper  
- Front grille 1612.00  
- Lower lip front bumper 759.00

## REPAIR DETAILS

### Reference

Part Source: MRM-SG      Version: 1.0 (Last Synchronised: 12 Sep 2022)  
 Parts: 143      AUDI A4 2.0 SEDAN TFSI S-TRONIC (NAV) (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's      (Price-denominated Standard List)  
 Print Code: Goldbell Engineering Pte Ltd/SMZ9596Y/12/09/2022 10:20  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	<i>Am</i> ✓ *1,100.00 F
2	1		*FRONT BUMPER GRILL	0.00	0.00	<i>Am</i> ✓ *580.00 F
3	1		*FRONT REINFORCEMENT	0.00	0.00	<i>bt</i> ✓ *465.00 F
4	1		*FRONT NO. PLATE WITH HOLDER	0.00	0.00	<i>Am</i> ✓ *35.00 F
<b>Total Parts (S\$)</b>						<b>2,180.00</b>

F=Franchise part.

Goldbell Engineering Pte Ltd/SMZ9596Y/12/09/2022 10:20. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items


There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	RESPRAY FRONT BUMPER	New	250 350.00
2	REMOVE INSTALL FRONT BUMPER, FRONT GRILL AND REINFORCEMENT.	New	250 450.00
<b>Gross Labour Cost (\$\$)</b>			<b>800.00</b>

Goldbell Engineering Pte Ltd/SMZ9596Y/12/09/2022 10:20. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

Tanfah 97495749  
Not Authorise  
Ex: Hbn  
Resurvey before paint.  
o3e4y5  
tanfah@lkkauto.com