

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22008772/ENY3Q2**Date:** 04/11/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00085362200

Claimant Vehicle No : SLJ682L **Insured Vehicle No :** SJZ4346X

Date of Loss: 31/08/2022 Nature of Claim: TP Claim No: SNM22D206216/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ682L**

Make & Model: NISSAN ALMERA, 1.5 (A) Engine No: HR15935553D

Reg. Date: 28/11/2016 (Man. Year: 2016) Chassis No: MNTBBAN17Z0005652

Colour: Brown Odometer: 139702 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15

Front Left Side: Goodyear 4 mm Rear Left Side: Goodyear 4 mm

Front Right Side: Goodyear 4 mm Rear Right Side: Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,010.13	602.56	407.57	40.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,673.00	1,345.00	328.00	19.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,683.13	1,947.56	735.57	27.41
+ GST 7.00/7.00% (S\$)	187.82	136.33	51.49	27.41
Nett Amount (S\$)	2,870.95	2,083.89	787.06	27.41

INSPECTION

Date of Assignment: 06/09/2022

Date Inspected: 27/09/2022 Inspected At: Tan Chong Motor Sales Pte Ltd (Bukit Timah)
911, Bukit Timah Road
Singapore 589622

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Nov 2022)
Parts:	143	NISSAN ALMERA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ682L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REVERSE SENSOR	Not Necessary	144.85 FS	*- FS
2	1		*EMBLEM T/LID	Necessary	62.20 FN	*62.20 FN
3	1		*EMBLEM	Necessary	62.20 FN	*62.20 FN
4	1		*BRACKET -BUMP LH	Not Necessary	44.00 FN	*- FN
5	1		*BRACKET -BUMP RH	Not Necessary	44.00 FN	*- FN
6	1		*ENERGY ABSORBER	Not Necessary	152.90 FN	*- FN
7	2		*GROMMET	Necessary	3.60 FN	*3.60 FN
8	10		*CLIP	Necessary	14.00 FN	*14.00 FN
9	1		*BUMPER	Cracked	586.20 FN	*586.20 FN
10	1		*REAR LICENCE PLATE	Not Necessary	60.00 FS	*- FS
11	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
					F=Franchise part. S=SpcNett. N=NettItemDisc.	
					Sub Total (\$\$)	1,203.95 748.20
					- Nett Item Discount on N Items 20.00/20.00% (\$\$)	193.82 145.64
					Total Parts (\$\$)	1,010.13 602.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	New	120.00	120.00
2	R/INSTALL OR RENEW REVERSE SENSOR ASSIST TO REPAIR	New	55.00	55.00
3	CHECK LIGHTING	New	48.00	0.00
4	REPAIR RR END PANEL & TRUNKLID RENEW RR BUMPER	New	700.00	420.00
5	S/PAINT RR END PANEL ,TRUNKLID & RR BUMPER	New	750.00	750.00
Gross Labour Cost (\$)			1,673.00	1,345.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >