



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3576
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co Reg No: 198003963G

Page 1 / 2

ESTIMATE

Date : 07/09/2022
To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Attn. : Steve (LKK)
Office / Mobile : 8/9/22, 10.00
Email Address : 10 8 dgr
From : GOLDBELL ENGINEERING PTE LTD
Attn. : CATHERINECHONGKL
Office / Mobile :
Email / Fax No. : CatherineChongKL@goldbell.com.sg

Reg No : PC97295
Model : TOYOTA / HIACE COMMUTER GL 3.0 A W/CHAIR LIFTER
Chassis No : KDH2230035179
Engine No : 1KD2777537
Quotation No. : 163738
Ref. No. : GBE/SVC/SALES-HQ/225-2608
D.O.A. : 26/08/2022
Policy No. : DMB1SNA0005512202
Claim Type : TP CLAIM - CHINA TAIPING INSURANCE
Workshop : 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		REAR FENDER LH	1	1,640.40	-10	1,476.36	1,476.36
2		TAILGATE	1	2,164.80	-10	1,948.32	1,948.32
3		REAR WINDSCREEN	1	1,466.30	-10	1,319.67	1,319.67
4		SMALL CENTER GLASS	1	883.50	-10	795.15	795.15
5		REAR FENDER GLASS	1	1,350.90	-10	1,215.81	1,215.81
PARTS TOTAL :							6,755.31

SPECIAL NETT ITEMS

1	COMPANY STICKER	1	600	800.00
2	REAR WINDSCREEN SEALANT	4	120	160.00
PARTS TOTAL :				960.00

LABOUR CHARGES

1	TO REMOVE AND REFIX REAR WINDSCREEN	120	150.00
2	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	1600	1800.00
3	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	800	1000.00
4	REMOVE AND REFIX SIDE FENDER GLASS	150	150.00

LABOUR TOTAL : 3,100.00
SUB-TOTAL : 10,815.31
GST @ 7% for \$ 10,815.31 757.07
GRAND TOTAL (\$\$) : 11,572.38

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

FUSO AIRMAN.

bizSAFE
STAR

