



2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SLD9387L

Model:

NISSAN X TRAIL

DOA : 2/9/2022

30/6/2016

Location : BKE TOWARDS PIE

3P:

SML8057S (ALLIANZ)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper	717		947.00
2	16 pcs	Rear bumper clips		80.00	1280.00
3	3pcs	Rear bumper clips (middle)		30.00	90.00
4	2 pcs	Rear bumper o/s & n/s retainer	177.50	L4x	355.00
5	1 pc	Rear bumper tow cover	60		103.00
6	1 pc	Rear bumper reinforcement	454		893.90
7	1 pc	Rear bumper sponge			190.40
8	2 pcs	Rear bumper o/s & n/s reflector			243.00
9	1 pc	Rear bumper lower diffuser			310.40
10	1 pc	Rear bumper lower diffuser garnish			280.00
11	1 pc	Rear tailgate			3460.00
12	1 pc	Rear tail gate inner trim			650.20
13	12pcs	Rear tail gate inner trim clips		60.00	720.00
14	1 pc	Rear tailgate lock			445.60
15	2pcs	Rear tailgate o/s & n/s shock absorber			810.40
16	2pcs	Rear tailgate o/s & n/s reflector			820.00
17	1 pc	Rear windscreen moulding		160.00	160.00
18	1 pc	Windscreen sealant		100.00	100.00
19	1 pc	Rear weather strip			190.70
20	2 pcs	Rear o/s & n/s tail lamp	462.00	L4x	924.00
21	1 pc	Rear end panel	541		820.00
22	1 pc	Rear end panel inner trim			245.40
23	1 pc	Rear boot floor panel			1252.50
24	1 pc	Rear boot floor panel insulator		300.00	300.00
25	2pcs	Rear o/s & n/s tool sponge			420.60
26	1 pc	Rear exhaust			
27	3pcs	Rear exhaust mounting			
28	1 pc	Rear exhaust heat shield			

2pcs Rear Reinforcement o/s & n/s stay \$360 bt-

29	2 pcs	Rear o/s & n/s wheel arch garnish		LHX	RM	650.40	325.20
30	2 pcs	Rear o/s & n/s wheel guard				670.40	X
31	1 pc	Rear QASHQAI' emblem				108.00	241
32	1 pc	Rear XTRONIC CVT emblem				80.20	241
33	1 pc	Rear 'Nissan' emblem				101.00	241
34	2 pcs	Rear reverse sensor				580.00	
			4552.70	0.00	1,310.00	14,972.10	
			10% - 4097.43	30%	0%	10%	
		After Less %:	0.00		1310.00	13474.89	
		<u>Labour</u>					
1		To dismantle damaged parts, straighten & welding.			1400.00	600	
2		To spray painting.			1200.00	700	
3		To remove & replace rear exhaust.			150.00	X	
4		To remove and refit rear upholstery to facilitate repair			100.00	60	
5		To remove & refit rear windscreen			150.00	120	
6		To remove & replace rear reverse sensor camera.			80.00	60	
7		To remove and replace rear tail gate			100.00	X	
8		To check for fault code & re-set electrical system.			280.00	X	
9		To check wiring.			180.00	30	
10		To re-seal anti-rust.			100.00	30	
		Sub Total:			3,740.00	1600	
		Total:			18,524.89		
		After Less 20%:			14,819.91		

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

Taufik 97495749
wp 7/9/22 @ 430 pm
L/S Resurvey after repair
taufik@khairto.com
05 days



AL 8778 1999
24 hr accident call



4097.43

50

1600

5747.43

4544600

05 days
#

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: