

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ALLIANZ INSURANCE SINGAPORE PTE LTD

79 Robinson Road #09-01

Singapore 068897

Date:

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01-61

SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

Quotation

DATE : 10.10.2022
VEH NO : PC7269R
MODEL : Toyota Hiace
D O A : 04.09.2022
YR REF : SKA1510C

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR PC7269R (TOYOTA HIACE)

Item	Description	Qty	Amt
------	-------------	-----	-----

LIST ITEMS

1	Front Bumper <i>Dehd</i>	1	673.20 ✓
2	Front Bumper Side Holder - LH <i>new</i>	1	85.40 +
4	Headlamp - LH <i>new</i>	1	2,326.70 +
3	Front Door - LH <i>Dehd</i>	1	1,571.80 ✓
4	Step Panel Garnish - LH <i>new</i>	1	258.80 x

4,915.90

Less 25%

(1,228.98)

3,686.93

S/NETT ITEMS

1	Front Bumper Clips <i>new</i>	1 set	30.00 ✓
2	Step Panel Garnish Clips <i>new</i>	1 set	20.00 x

Total Parts

\$ 3,736.93

LABOUR CHARGE

1	To knocking & pull out front portion & renew parts	\$ 600.00 <i>400</i>
2	To putty & spray up paint works	\$ 600.00 <i>400</i>
3	To check wiring	\$ 50.00 <i>30</i>
4	To spray tuff coat	\$ 150.00 <i>20</i>
5	To transfer door fittings	\$ 150.00 <i>80</i>

Total Labour

\$ 1,550.00

Grand Total

\$ 5,286.93

total: 2643.75
L/S: 2.11K. 03Pyr