



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2301480  
INV Date 13/03/2023  
Reference CC4/LPC22008785/Epa3q2  
Code LPC2

#### PROFESSIONAL SERVICE FEE

Vehicle No. SGM 3000D  
Insured Veh. GZ 9164G  
Claim No. 21/22/22/VC00/026239  
Policy No. Z/21/VC00/112471  
Accident Date 01/09/2022  
Inspection Date 07/09/2022

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (8%)</b>                | <b>32.00</b>  |
| <b>Grand Total</b>             | <b>432.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CC4/LPC22008785/Epa3q2

Date: 13/03/2023

Code: LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |                      |                       |            |
|---------------------|----------------------|-----------------------|------------|
| <b>Insured Veh.</b> | GZ 9164G             | <b>Veh. Inspected</b> | SGM 3000D  |
| <b>Policy No.</b>   | Z/21/VC00/112471     | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | 21/22/22/VC00/026239 | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | GERALD               | <b>Assign Date</b>    | 07/09/2022 |

### 2. Vehicle Particulars & Condition

|                         |                    |                     |            |
|-------------------------|--------------------|---------------------|------------|
| <b>Make &amp; Model</b> | MERCEDES BENZ E200 | <b>c.c</b>          | 1991       |
| <b>Engine No.</b>       | HIDDEN             | <b>Year of Reg.</b> | 2019       |
| <b>Chassis No.</b>      | WDD2130422A541998  | <b>Colour</b>       | BLACK      |
| <b>Odometer</b>         | 47555 KM           | <b>Steering</b>     | IN ORDER   |
| <b>Brakes</b>           | IN ORDER           | <b>Modification</b> | SPORTS RIM |
| <b>General</b>          | FAIR               |                     |            |

### 3. Conditions of Tyres

|                       | Size       | Make        | Balance |
|-----------------------|------------|-------------|---------|
| <b>R/H Front Tyre</b> | 225/55 R17 | BRIDGESTONE | 5 mm    |
| <b>L/H Front Tyre</b> | 225/55 R17 | BRIDGESTONE | 5 mm    |
| <b>R/H Rear Tyre</b>  | 225/55 R17 | BRIDGESTONE | 5 mm    |
| <b>L/H Rear Tyre</b>  | 225/55 R17 | BRIDGESTONE | 5 mm    |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

### 5. General Information

|                       |   |                        |            |
|-----------------------|---|------------------------|------------|
| <b>Accident Date</b>  | 01/09/2022  | <b>Inspection Date</b> | 07/09/2022 |
| <b>Survey held at</b> | ACCORD AUTO SERVICES PTE LTD<br>BLK 1009 BUKIT MERAH LANE 3<br>#01-80<br>SINGAPORE 159723 |                        |            |

### 5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **10 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGM 3000D

| Qty                                | Description of Parts  | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|----------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |   |                      |                           |                   |
| 1                                  | FRONT LH SIDE MIRROR ASSY   | BROKEN               | 1,850.00                  | 1,028.00          |
| 1                                  | FRONT LH DOOR   | DENTED               | 2,650.00                  | 2,300.00          |
| 1                                  | FRONT LH DOOR INNER TRIM BOARD  | BROKEN               | 1,780.00                  | 1,208.00          |
| 2                                  | FRONT LH DOOR HINGE   | NOT NECESSARY        | 170.00                    | -                 |
| 1                                  | FRONT LH DOOR CHECKER   | NOT NECESSARY        | 90.00                     | -                 |
| 1                                  | FRONT LH DOOR OUTER HANDLE  | CUT                  | 138.60                    | 138.60            |
| 1                                  | FRONT LH DOOR PILLAR GARNISH  | NOT NECESSARY        | 125.68                    | -                 |
| 1                                  | SET FRONT LH DOOR TRIM BOARD RIVET PIN  | NECESSARY            | 80.00                     | 30.00             |
| 1                                  | FRONT LH DOOR RUBBER  | NECESSARY            | 275.00                    | 275.00            |
| 1                                  | REAR LH DOOR  | DENTED               | 2,500.00                  | 2,337.00          |
| 2                                  | REAR LH DOOR HINGE  | NOT NECESSARY        | 170.00                    | -                 |
| 1                                  | REAR LH DOOR RUBBER   | NOT NECESSARY        | 297.00                    | -                 |
| 1                                  | REAR LH DOOR RUBBER (FRONT)   | TORN                 | 168.00                    | 168.00            |
| 1                                  | SET REAR LH DOOR TRIM BOARD RIVET PIN   | NECESSARY            | 80.00                     | 30.00             |
| 1                                  | REAR LH DOOR PILLAR GARNISH   | NOT NECESSARY        | 185.00                    | -                 |
| 1                                  | REAR LH FENDER  | TO REPAIR SEE LABOUR | 2,100.00                  | -                 |
| 1                                  | SET REAR WINDSCREEN MOULDING  | NECESSARY            | 300.00                    | 200.00            |
|                                    | LESS 10% DISCOUNT   |                      | -1,295.93                 | -771.46           |
|                                    |   |                      | 11,663.35                 | 6,943.14          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |   |                      |                           |                   |
| 1                                  | WINDSCREEN SEALANT (SN)   | NECESSARY            | 100.00                    | 40.00             |
| 1                                  | SET REAR FENDER SHIELD CLIPS (SN)   | NECESSARY            | 50.00                     | 30.00             |
|                                    |   |                      | 150.00                    | 70.00             |
| <b><u>LABOUR</u></b>               |   |                      |                           |                   |
|                                    | SPRAY PAINTING TO ALL AFFECTED AREAS (INCLUDING INNER CENTRE PANEL).  |                      | 1,200.00                  | 1,000.00          |
|                                    | LABOUR REMOVE /REFIX ACCIDENT DAMAGES PARTS TO KNOCK ,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA .INCLUSIVE OF THE REPAIR OF REAR LH FENDER . |                      | 1,600.00                  | 1,200.00          |
|                                    | CHECK WIRING SYSTEM & LIGHT.  | NOT NECESSARY        | 100.00                    | -                 |

Report Ref No. CC4/LPC22008785/Epa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                | Description of Parts  | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|---------------|---------------------------|-------------------|
|                                    | ANTI RUST TREATMENT .   | NOT NECESSARY | 120.00                    | -                 |
|                                    | TO CHECK & ADJUST WHEEL ALIGNMENT.  | NOT NECESSARY | 100.00                    | -                 |
|                                    | TO REMOVE /REFIX FRONT LH DOOR WINDOW GLASS ,MECHANISM & ASSY TO NEW DOOR . |               | 200.00                    | 80.00             |
|                                    | TO REMOVE/REFIX REAR LH DOOR WINDOW GLASS ,MECHEMISM & ASSY TO NEW DOOR.    |               | 200.00                    | 80.00             |
|                                    | TO REMOVE /REFIX REAR WINDSCREEN TO REPLACE REAR LH FENDER .                |               | 150.00                    | 120.00            |
|                                    | TO REMOVE/REFIX INNER COMPARTMENT & CARPET TO FACILITATE REPAIR .           |               | 280.00                    | 80.00             |
|                                    | COMPUTER DIAGNOSTIC (RESET NECESSARY ELECTRONIC FUNCTION).                  |               | 350.00                    | 150.00            |
|                                    |   |               | 4,300.00                  | 2,710.00          |
| <b>GRAND TOTAL</b>                 |   |               | <b>16,113.35</b>          | <b>9,723.14</b>   |
| <b>RECOMMENDED COST OF REPAIRS</b> |   |               |                           | <b>9,723.14</b>   |

Report Ref No. CC4/LPC22008785/Epa3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SGM 3000D

## INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SGM 3000D

## RE-INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SGM 3000D**

**RE-INSPECTION**

