

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22008786/GVY3Q2**Date:** 21/09/2022REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MN000213

Claimant Vehicle No : SHC1338J**Insured Vehicle No :** SLH6539P

Date of Loss: 06/09/2022

Nature of Claim: TP Claim No: M2204862

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHC1338J**

Make & Model: TOYOTA PRIUS TAXI, 1.8 (A)

Engine No: 2ZRS061041

Reg. Date: 10/08/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU603563230

Colour: Blue

Odometer: 817699 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Davanti 6 mm

Rear Left Side: Davanti 6 mm

Front Right Side: Davanti 6 mm

Rear Right Side: Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,127.27	2,619.10	1,508.17	36.54
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,170.00	1,760.00	410.00	18.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,308.27	4,390.10	1,918.17	30.41
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	6,308.27	3,500.00	2,808.27	44.52
+ GST 7.00/7.00% (S\$)	441.58	245.00	196.58	44.52
Nett Amount (S\$)	6,749.85	3,745.00	3,004.85	44.52

INSPECTION

Date of Assignment: 07/09/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 07/09/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2022)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC1338J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Buckled	1,111.93 FL	*1,111.93 FL
2	1		*FRONT FENDER SHIELD RH	Deformed	198.50 FL	*198.50 FL
3	1		*FRONT FENDER EMBLEM RH	Necessary	86.50 FL	*86.50 FL
4	1		*FRONT DOOR PANEL RH	Buckled	1,264.00 FL	*1,264.00 FL
5	1		*REAR DOOR PANEL RH	Repair	1,258.30 FL	*- FL
6	1		*ROCKER GARNISH RH	Repair	752.60 FL	*- FL
7	1		*FRONT DOOR HINGE LOWER	Bent	91.20 FL	*91.20 FL
8	1		*FRONT DOOR COMFORT LOGO STICKER	Necessary	75.00 FS	*75.00 FS
9	1		*REAR DOOR COMFORT APP LOGO STICKER	Necessary	80.00 FS	*80.00 FS
10	1		*REAR DOOR ADVERTISEMENT	Necessary	100.00 FS	*100.00 FS
11	1		*FRONT DOOR ADVERTISEMENT	Necessary	100.00 FS	*100.00 FS
12	1		*FRONT FENDER ADVERTISEMENT	Necessary	100.00 FS	*100.00 FS
13	1		*REAR FENDER ADVERTISEMENT	Necessary	100.00 FS	*100.00 FS
					Sub Total (\$\$)	5,318.03 3,307.13
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,190.76 688.03
					Total Parts (\$\$)	4,127.27 2,619.10

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,050.00	700.00
2	SPRAY PAINTING	New	1,000.00	1,000.00
3	TRANFER DOOR PARTS	New	120.00	60.00
Gross Labour Cost (\$\$)			2,170.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >