

Steve

ASSIGNMENT

Date:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV



Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 63111
Date Estimated : 29/08/2022
Prepared By : Yap Mee Key

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Tang Jingping
75 Jurong East Street 13
#04-02

Singapore 609652

- ACCOUNT - 303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKV1711D	WBA2A32030V458541	31/08/2015	2181A AT	62516

DESCRIPTION	VALUE
To replace tailgate, rear bumper carrier, rear bumper and tail panel.	1600 4,675.00
To respray tailgate and rear bumper.	1972 2,076.00
To carry out body cavity preservation. (Per panel).	112 118.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168 177.00
To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.	504 531.00
To check electrical.	168 177.00
To replace rear windscreen glass.	545 574.00
To supply and install rear windscreen solar film.	504 531.00
To replace rear exhaust silencer including alignment system and conduct check for leak.	? 531.00
To conduct water leak tests.	71 75.00
To carry out body cavity preservation. (For cut panel).	? 531.00
Sundries.	150.00

Total Labour 1: 10,146.00

DESCRIPTION	QTY	PRIC	VALUE
RUBBER MOUNTING	2	18.15	36.30

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 63111
Date Estimated : 29/08/2022
Prepared By : Yap Mee Key

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKV1711D	WBA2A32030V458541	31/08/2015	218iA AT	62516

DESCRIPTION	QTY	PRIC	VALUE
REAR SILENCER	1	1,030.30	1,030.30
TAILPIPE TRIM CHROME	1	119.60	119.60
HOLDER EXHAUST SYSTEM	2	62.10	124.20
TRUNK LID	1	1,257.95	1,257.95
TAIL PANEL	1	390.35	390.35
REAR BUMPER PANEL PRIMED (PDC)	1	1,050.55	1,050.55
REAR BUMPER CARRIER	1	490.70	490.70
SUPPORT	1	47.00	47.00
LH ADDITIONAL TURN INDICATOR LAMP	1	64.10	64.10
RH ADDITIONAL TURN INDICATOR LAMP	1	64.10	64.10
BUMP STOP	10	3.30	33.00
REAR FLAP TOWING EYE PRIMED	1	43.95	43.95
REAR FLAP TOWING EYE PRIMED	1	43.95	43.95
REAR WINDOW ESG	1	630.20	630.20
TRUNK LID SEALING	1	97.85	97.85
RR LH LIGHT IN THE TRUNK LID	1	267.40	267.40
RR RH LIGHT IN THE TRUNK LID	1	267.40	267.40
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10

Total Parts : 6,348.15

Steve (LKK)
12/9/22, 1-3pm

W m
P/P
by Bul by
5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Acknowledged by Repairer
Signature:
Date:

Labour 1	:	10,146.00
Parts	:	6,348.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,154.59
Grand Total	:	17,648.74

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **